

**NM OIL CONSERVATION**

ARTESTA DISTRICT

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

JUN 14 2016

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.  
**RECEIVED**

**Release Notification and Corrective Action**

*DAB16110740309*

**OPERATOR**  Initial Report  Final Report

<b>Name of Company</b> Devon Energy Production Company <i>1137</i>	<b>Contact</b> Matt Nettles, Production Foreman
<b>Address</b> 6488 Seven Rivers Hwy Artesia, NM 88210	<b>Telephone No.</b> 575.513.5767
<b>Facility Name</b> Remuda Basin SWD 1	<b>Facility Type</b> Salt Water Disposal
<b>Surface Owner</b> Federal	<b>Mineral Owner</b> Federal
<b>API No</b> 30-015-29549	

**LOCATION OF RELEASE**

Unit Letter D	Section 20	Township 23S	Range 30E	Feet from the 330	North/South Line FNL	Feet from the 660	East/West Line FWL	County Eddy
------------------	---------------	-----------------	--------------	----------------------	-------------------------	----------------------	-----------------------	----------------

**Latitude:** 32.2966716

**Longitude:** -103.90964

**NATURE OF RELEASE**

<b>Type of Release</b> Produced Water	<b>Volume of Release</b> 500BBS	<b>Volume Recovered</b> 480BBS
<b>Source of Release</b> Injection Pump	<b>Date and Hour of Occurrence</b> 6/12/2016 @ 2:30PM	<b>Date and Hour of Discovery</b> 6/12/2016 @ 2:30PM
<b>Was Immediate Notice Given?</b> <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	<b>If YES, To Whom?</b> BLM-Shelly Tucker OCD-Mike Bratcher	
<b>By Whom?</b> Jeremy Porras, Assistant Production Foreman	<b>Date and Hour</b> BLM-6/12/2016 @ 2:33PM OCD-6/12/2016 @ 2:35PM	
<b>Was a Watercourse Reached?</b> <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	<b>If YES, Volume Impacting the Watercourse</b> N/A	
<b>If a Watercourse was Impacted, Describe Fully.*</b> N/A		
<b>Describe Cause of Problem and Remedial Action Taken.*</b> As a result of mechanical failure injection pump failed to kick on and alarms were not activated resulting in 500BBS of PW overflowing from the tanks. Produced water was also diverted another water disposal to prevent further release. Communication problem has been resolved.		
<b>Describe Area Affected and Cleanup Action Taken.*</b> 500BBS of pw was released as a result of the tanks overflowing. The release flowed in a southwestern direction and did reach the pasture. 480BBS pw was recovered via vacuum truck. The approximate size of the total affected area was a 500ft by 500ft. An environmental company will be contacted for remediation.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
<b>Signature:</b> <i>Dana DeLaRosa</i>	<b>OIL CONSERVATION DIVISION</b>	
<b>Printed Name:</b> Dana DeLaRosa	Signed By: <i>M/L DeLaRosa</i> Approved by Environmental Specialist:	
<b>Title:</b> Field Admin Support	<b>Approval Date:</b> <i>6/14/16</i>	<b>Expiration Date:</b> <i>N/A</i>
<b>E-mail Address:</b> dana.delarosa@dvn.com	<b>Conditions of Approval:</b>	
<b>Date:</b> 6/13/2016 <b>Phone:</b> 575.746.5594	<b>Remediation per O.C.D. Rules &amp; Guidelines</b> Attached <input type="checkbox"/> <b>SUBMIT REMEDIATION PROPOSAL NO</b> <b>LATER THAN:</b> <i>7/15/16</i> <i>GRP-3743</i>	

\* Attach Additional Sheets If Necessary

**Bratcher, Mike, EMNRD**

---

**From:** DeLaRosa, Dana <Dana.DeLaRosa@dvn.com>  
**Sent:** Monday, June 13, 2016 2:11 PM  
**To:** Tucker, Shelly; Bratcher, Mike, EMNRD  
**Subject:** Remuda Basin SWD 1\_500BBLs PW\_6.12.6  
**Attachments:** Remuda Basin SWD 1\_500BBLs PW\_GIS Image\_6.12.16.pdf; Remuda SWD 1\_500BBLs PW\_6.12.16\_Initial C141.doc; Pic 1 of 12.JPG; Pic 2 of 12.JPG; Pic 3 of 12.JPG; Pic 4 of 12.JPG; Pic 5 of 12.JPG; Pic 6 of 12.JPG; Pic 7 of 12.JPG; Pic 8 of 12.JPG; Pic 9 of 12.JPG; Pic 10 of 12.JPG; Pic 11 of 12.JPG; Pic 12 of 12.JPG

Attached is the Initial C141, GIS Image and photos for the 500BBL produced water release that occurred on 6.12.2016 at the Remuda Basin SWD 1. The red dot on the GIS Image represents the approximate origin of release.

*Dana DeLaRosa*

Field Admin Support  
Production  
B-Schedule



Devon Energy Corporation  
PO Box 250  
Artesia, NM 88211  
575-746-5594

Confidentiality Warning: This message and any attachments are intended only for the use of the intended recipient(s), are confidential, and may be privileged. If you are not the intended recipient, you are hereby notified that any review, retransmission, conversion to hard copy, copying, circulation or other use of all or any portion of this message and any attachments is strictly prohibited. If you are not the intended recipient, please notify the sender immediately by return e-mail, and delete this message and any attachments from your system.