

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141
Revised August 8, 2011

Submit Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

NAB 1631050720
Name of Company: COG Operating LLC *229137* Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701 Telephone No. 432-683-7443
Facility Name: SHOWSTOPPER 7 FEDERAL COM #001H Facility Type: Well

Surface Owner: Federal Mineral Owner: Federal API No. 30-015-36559

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	7	25S	29E	330'	North	480'	East	Eddy

Latitude/Longitude 32.1511154,-104.0167618

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 20 bbls PW	Volume Recovered: 0 bbls PW
Source of Release: Poly Flowline Leak	Date and Hour of Occurrence: 7/16/2016, unknown	Date and Hour of Discovery: 7/16/2016 8:00 am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

This release was caused by a ruptured poly flowline. Although a vacuum truck was dispatched, due to the hot weather no fluid was recoverable.

Describe Area Affected and Cleanup Action Taken.*

This release occurred in the pasture along the road in section 8. It impacted approximately 3500 sq ft. Concho will have the spill site sampled to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Amanda T. Davis</i>	OIL CONSERVATION DIVISION	
Printed Name: Amanda Trujillo Davis	Approved by Environmental Specialist: <i>H. C. Davis</i>	
Title: Senior Environmental Coordinator	Approval Date: 7/25/16	Expiration Date: N/A
E-mail Address: atrujillo@concho.com	Conditions of Approval:	
Date: July 22, 2016 Phone: 575-748-6940	Remediation per O.C.D. Rules & Guidelines SUBMIT REMEDIATION PROPOSAL NO LATER THAN: 9/1/16	

* Attach Additional Sheets If Necessary

Attached ☐

2RP-3802

Patterson, Heather, EMNRD

From: Amanda Trujillo Davis <ATrujillo@concho.com>
Sent: Friday, July 22, 2016 5:56 PM
To: Patterson, Heather, EMNRD; Bratcher, Mike, EMNRD; James_Amos@blm.gov; Shelly Tucker
Subject: (Notification/C-141 Initial/Form3160-5/Arc) SHOWSTOPPER 7 FEDERAL COM #001H (30-015-36559)
Attachments: 7-16-2016 Showstopper 7 Federal Com #1H (FL) Initial.pdf; FORM 3160-5 30-015-36559 7-16-2016.pdf

Mr. Bratcher/ Ms. Tucker,

COG Operating LLC is reporting a release on the SHOWSTOPPER 7 FEDERAL COM #001H (30-015-36559)
Unit A Section 07 Township 25S Range 29E
The release occurred on 7/16/2016
Estimated Released: 20 bbls PW
Recovered: 0 bbls PW

This release was caused by a ruptured poly flowline. Although a vacuum truck was dispatched, due to the hot weather no fluid was recoverable. This release occurred in the pasture along the road in section 8. It impacted approximately 3500 sq. ft. Attached are a BLM Form 3160-5, map of the area and a copy of the C-141 for your consideration. I'd like to also request Arc clearance for this location at this time as well. If you have any additional questions please feel free to contact me.

Thank you,

Amanda Trujillo Davis
Senior Environmental Coordinator
COG Operating LLC
Cell: 505.350.1336
Office: 575.748.6930
atrujillo@concho.com

1401 Commerce Drive
Carlsbad, NM 88220



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information herein, is prohibited. If you received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained

herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.