



AE Order Number Banner

Report Description

This report shows an AE Order Number in Barcode format for purposes of scanning. The Barcode format is Code 39.



App Number: pJXK1621155176

1RP - 2770

LEGACY RESERVES OPERATING LP

7/29/2016

HOBBS OCD

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action**OPERATOR**☒ Initial Report ☐ Final Report

Name of Company	Legacy Reserves Operating LP	Contact	Berry Johnson
Address	P.O. Box 10848 Midland, TX 79702	Telephone No.	432-689-5219
Facility Name	Jalmat Yates Unit #17	Facility Type	Oil
Surface Owner	Greg Fulfer	Mineral Owner	
		Lease No.	309054

LOCATION OF RELEASE API # 30-025-11648-00-00

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
C	18	25S	37E	660	North	1980	West	Lea

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release	oil & water	Volume of Release	50 bbls	Volume Recovered	0
Source of Release	2" steel flowline	Date and Hour of Occurrence	5/19	Date and Hour of Discovery	5/19/11-10 AM
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Land Owner - Greg Fulfer OCD - Jeff Leking		
By Whom?	Tommy Hill - Berry Johnson	Date and Hour	5/19/2011 - 4 PM		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

GWA 115'



Describe Cause of Problem and Remedial Action Taken.*

Property bought from COG. Well was in test & result was low. Found leak in pasture from old 2" flowline. Will replace with 2" SDR 7 poly. We S/I well & notified land owner & OCD.

Describe Area Affected and Cleanup Action Taken.*

Pasture land approx. 20' wide x 150' long, then ran 600' down cow trail x 2' wide. Fenced area off & contacted E-Tech Environmental for remediation plans.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Berry Johnson	Approved by ENV SPECIALIST:  District Supervisor:	
Title: Production Superintendent	Approval Date: 05/24/11	Expiration Date: 07/25/11
E-mail Address:	Conditions of Approval: submit FINAL C-141 BY 07/25/11	Attached <input type="checkbox"/> IRP-12-11-2770
Date: 05/20/11 Phone: 432-689-5200		

* Attach Additional Sheets If Necessary

JAN 03 2012