



AE Order Number Banner

Report Description

This report shows an AE Order Number in Barcode format for purposes of scanning. The Barcode format is Code 39.



App Number: pJXK1621139578

1RP - 4376

NEW MEXICO SALT WATER DISPOSAL CO., INC

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: New Mexico Salt Water Disposal Co.	Contact:
Address: P.O. Box 1518 Roswell, NM 88202	Telephone No.:
Facility Name: Simanola Main Station #11	Facility Type: Battery

Surface Owner: State	Mineral Owner	Lease No.:
----------------------	---------------	------------

LOCATION OF RELEASE

Unit Letter D	Section 21	Township 10S	Range 34E	Feet from the 737'	North/South Line NORTH	Feet from the 740'	East/West Line WEST	County LEA
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	---------------

Latitude: 33.437726

Longitude: -103.475164

NATURE OF RELEASE



Type of Release: produce water and oil	Volume of Release:	Volume Recovered:
Source of Release: separation of dresser sleeve on 3" poly line	Date and Hour of Occurrence: between 5p 4-20-11 & 1025am 4-21-11	Date and Hour of Discovery: 1025am 4-21-11
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom? William V. Palmer Superintendent	Date and Hour:	
Was a Watercourse Reached? AMENDED <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* dresser sleeve on 3"poly line parted, pipe reassembled and secured with 1/4" chain and boomer. Water truck immediately called for water collection, and disposed of properly.

Describe Area Affected and Cleanup Action Taken.* overspray on lease rd. and pasture NW corner of battery, area 1,375sqft, 600sqft lease rd. SE corner of battery, 3,535sqft pasture S & SE of battery. Total area outside of battery 4,910sqft. All other water remained inside of battery berm. Site is presently being scheduled for battery clean up and remediation by Whole Earth Environmental Inc.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: William V. Palmer 	OIL CONSERVATION DIVISION	
Printed Name: William V. Palmer	Approved by ^{ENV. ENGINEER:} District Supervisor: 	
Title: Manager	Approval Date: 05/20/11	Expiration Date: 07/20/11
E-mail Address: wpalmer@read-stevens.com	Conditions of Approval: DELINQUENT TO CLEAN UP. SUBMIT FINAL C-141 BY 07/20/11	Attached <input type="checkbox"/> 1RP-05-11-3112
Date: May 19, 2011	Phone: 575.396.7560	

* Attach Additional Sheets If Necessary