

AE Order Number Banner

Report Description

This report shows an AE Order Number in Barcode format for purposes of scanning. The Barcode format is Code 39.



App Number: pJXK1621534628

1RP - 2807
SOUTHERN UNION GAS COMPANY

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

* Attach Additional Sheets If Necessary

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Revised August 8, 2011 Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Form C-141

Release Notification and Corrective Action

			OPERATOR			☐ Initial Report ☐ Final Report							
							ose Slade						
						Telephone No.: 817.302.9716 or 432.940.5147							
Facility Na	me Monah	ans Field Of	fice			Facility Typ 1/25/2012	e: Natural Gas	Gather	ing/Trunk	"O" Pipeli	ne Lea	ak #3	
Surface Owner: Greg Fulfer/Larry Hammons Mineral Owner							API No. 30-025-2						
				LOCA	TION	OF RE	LEASE						
Unit Letter E	Section 19	Township 25S	Range 37E	Feet from the	North/	South Line	Feet from the	East/\	West Line	County Lea			
			Latitud	le_32 06.955'					_				
Type of Rele	ease: Crude	oil. Produced	Water, Na		KE	Volume of	Release: 150 bar	rels	Volume I	Recovered: 1	00 bar	rels	
Type of Release: Crude oil, Produced Water, Natural Gas Source of Release: Pipeline							Date and Hour of Occurrence: Unknown			Date and Hour of Discovery 1/25/2012 at approximately 8:00 am			
Was Immedi	iate Notice (Yes [No Not Req	uired	If YES, To	Whom? Geoffre	y Lekin	g				
By Whom? Rose Slade						Date and Hour 1/25/2012 at 9:30 am							
Was a Watercourse Reached? ☐ Yes ☑ No							If YES, Volume Impacting the Watercourse. HOBBS OCD						
If a Waterco	urse was Im	pacted, Descr	ibe Fully.	*					M	AR 2 6 2	013		
started the su	urface clean	-up of the rele	ase site ar	on Taken.* The 20" and put the impacted e. The landowners	soil or	nto plastic un	til further remedia				t the lea		
The impacte Sundance Se results indica remediated s the NOVA S	ed area was of ervices for d ated benzen stockpiled so Safety and E	isposal. The se, BTEX, TPI oil and locally invironmental	soil samp soil sampl I, and chl- obtained Remediat	es were collected f es were submitted to oride concentrations non-impacted soil. ion Summary and S	o the last were For further Clo	aboratory for less than NM orther details osure Request	benzene, BTEX, IOCD regulatory of the remediation dated March 201	TPH, and guideling activities 13.	nd chloride les. The ex- les conducte	analysis. La cavation was ed at the site	aborato s backf please	ory analytical filled with the reference	
regulations a public health should their or the enviro	all operators h or the envi operations l onment. In a	are required to ironment. The have failed to	o report a acceptan adequatel OCD acce	e is true and comple nd/or file certain rel ce of a C-141 repor y investigate and rel ptance of a C-141 re	ease n t by the nediat	otifications a e NMOCD n e contaminat	and perform corre- narked as "Final Fi ion that pose a thi	ctive act Report" of reat to g	tions for rel does not rel round wate	eases which ieve the ope r, surface wa	may en rator of ater, hu	ndanger f liability man health	
Signature: CA Stenly Printed Name: Curt Stanley							Approved by Environmental Specialist						
							Approval Date: 3/27/13 Expiration Date:						
200 000 000 0000		ınley@sug.co	m			Conditions of		_		Attached		14	
Date:3/27/2	013			Phone: 575 390 7	595					LPP-	5-17	-2807	