

NM OIL CONSERVATION

ARTESIA DISTRICT

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

AUG 02 2016

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1621756110

OPERATOR

Initial Report Final Report

Name of Company OXY USA WTP LP <i>192463</i>	Contact Jennifer Duarte
Address PO BOX 4294; HOUSTON, TX 77210	Telephone No. 713-513-6640
Facility Name STATE CV COM #1	Facility Type WELL
Surface Owner	Mineral Owner
API No. 30-015-21927	

LOCATION OF RELEASE

Unit Letter E	Section 16	Township 20S	Range 28E	Feet from the 1980	North/South Line NORTH	Feet from the 760	East/West Line WEST	County EDDY
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	----------------------	------------------------	----------------

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release GAS - FLARE	Volume of Release 3280 MCF	Volume Recovered 0
Source of Release GAS - FLARE	Date and Hour of Occurrence 07/28/2016 - BEGAN	Date and Hour of Discovery
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Flaring due to restart gas lift compressor.

Describe Area Affected and Cleanup Action Taken.*

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Jennifer Duarte</i>	OIL CONSERVATION DIVISION	
Printed Name: JENNIFER DUARTE	Signed By: <i>Mike [Signature]</i> Approved by Environmental Specialist:	
Title: ENVIRONMENTAL SPECIALIST	Approval Date: <i>8/2/16</i>	Expiration Date: <i>NA</i>
E-mail Address: jennifer_duarte@oxy.com	Conditions of Approval: FINAL	Attached <input type="checkbox"/>
Date: 08/02/2016	Phone: 713-513-6640	

* Attach Additional Sheets If Necessary

ARP-3706

Bratcher, Mike, EMNRD

From: Jennifer_Duarte@oxy.com
Sent: Tuesday, August 02, 2016 4:23 PM
To: Bratcher, Mike, EMNRD
Subject: FLARE C141s
Attachments: Scanned from a Xerox Multifunction Device001.pdf; Scanned from a Xerox Multifunction Device002.pdf

Importance: High

Please see the attached C141s for flaring events. Should you have any questions or concerns, please feel free to contact me at any time.

Thank you,
Jennifer Duarte
Environmental Specialist
713-513-6640