



# AE Order Number Banner

## Report Description

This report shows an AE Order Number in Barcode format for purposes of scanning. The Barcode format is Code 39.




**App Number: pTO1435156963**

**1RP - 3465**

**MARK L SHIDLER INC**

8/12/2016



MARK L. SHIDLER, INC.  
PETROLEUM EXPLORATION AND PRODUCTION

Certified Mail, RRR No.: 7012.2210 0002 3276 4094

HOBBSOCD

DEC 19 2014

RECEIVED

December 16, 2014

Oil Conservation Division  
Energy Minerals and Natural Resources  
State of New Mexico  
1625 N. French Drive  
Hobbs, New Mexico 88240

Re: State No. 1-30  
B-30-T12S-R34E  
High Tower Up. Penn East  
Lea Co., New Mexico

-----  
C-141 (initial)

Gentlemen:

Please find enclosed the initial filing of that certain C-141 dated December 16, 2014 for the State 1-30. The same sets out the release, discharge and emission of crude oil, natural gas and salt water which occurred between December 6 and 10, 2014. Also enclosed is MARK L. SHIDLER, INC.'s ("MLSI") *Rework Report* evidencing the separate events as well as ongoing remediation efforts and reference map for your review.

MLSI will be providing this office with periodic updates of the ongoing remediation efforts at the above Re well and surrounding area. You are welcome to contact me, at (713) 481-6487 or [ggregson@marklshidlerinc.com](mailto:ggregson@marklshidlerinc.com).

Very truly yours,  
MARK L. SHIDLER, INC.

Gregory B. Gregson  
Operations Manager

GBG

Encl.

RP-3465  
already  
file