

Bratcher, Mike, EMNRD

From: Paul Ragsdale <pragsdale@stratanm.com>
Sent: Friday, August 19, 2016 2:50 PM
To: Bratcher, Mike, EMNRD
Cc: Dwight Adamson; grace@stratanm.com
Subject: RE: Strata Chaparral Site
Attachments: C-141 - Chaparral #1 8-19-16.pdf

Mike,
Dwight tells me the cleanup is complete. I have attached a C-141 per your request.
Thanks,
Paul

From: Bratcher, Mike, EMNRD [mailto:mike.bratcher@state.nm.us]
Sent: Tuesday, August 9, 2016 4:52 PM
To: 'Paul Ragsdale' (pragsdale@stratanm.com)
Cc: Patterson, Heather, EMNRD; Bayliss, Randolph, EMNRD; Cordero, Gilbert, EMNRD; Groves, Amber
Subject: FW: Strata Chaparral Site

Paul,

An OCD field inspection was made on Strata's Chaparral State 1 site today. The attached photos are of what was observed. If the release volume was in excess of 5 bbls fluid, and/or 50 mcf gas, please send an Initial Report Form C-141. If less than 5 bbls, a C-141 is not required, however, OCD would ask that Strata advise OCD what the plan for clean-up will be.

Thank you,

Mike Bratcher
NMOCD District 2
811 S. First Street
Artesia, NM 88210
O: 575-748-1283 X108
C: 575-626-0857
F: 575-748-9720

From: Cordero, Gilbert, EMNRD
Sent: Tuesday, August 09, 2016 2:54 PM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD
Subject: Strata

Attached are some pictures of the Chaparral State #001. API 30-015-22028. It appears they had a release. There is oil spray over a large part of location, the pasture and also some run off downhill of location.

Thanks,

Gilbert Cordero
Compliance Officer
NMOCD District II