

SEP 21 2016

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

RECEIVED

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB116216736693 **OPERATOR** ☒ Initial Report ☐ Final Report

Name of Company: Devon Energy Production Co LP (6137)	Contact: Brian Kuh, Devon Completions Foreman
Address: PO Box 250 Artesia, NM 88211	Telephone No. 575-616-1540
Facility Name: Cotton Draw Unit 238H	Facility Type: Oil Well

Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-43269
-------------------------------	-------------------------------	-----------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
E	13	25S	31E	2560	North	140	West	Eddy

Latitude: **32.145352** Longitude: **-103.739623**

NATURE OF RELEASE

Type of Release: Treated Water	Volume of Release: 8 BBLs	Volume Recovered: 0 BBLs
Source of Release: Water Transfer Line	Date and Hour of Occurrence: 4/26/2016, 9:20 PM	Date and Hour of Discovery: 4/26/2016, 9:20 PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? BLM: Jim Amos	
By Whom? Brian Kuh, Devon Completions Foreman	Date and Hour: 4/27/2016, 1:50 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.* **N/A**

Describe Cause of Problem and Remedial Action Taken.*

A water transfer road crossing line was damaged by possible malicious mischief causing an 8 barrel spill of treated water on the lease road approximately 3220 feet to the north of the Cotton Draw Unit 238H. Line pinchers were applied to both the upstream and downstream lines to isolate the leak and the damaged line and left flange were replaced.

Describe Area Affected and Cleanup Action Taken.*

8 barrels of treated water were spilled on the lease road and 0 barrels were recovered. The spill ran in a southwest direction covering an approximate 40 foot by 40 foot area. The contaminated soil was placed on a plastic liner to prevent further leakage. An environmental company will be contacted for remediation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Denise Menoud</i>	OIL CONSERVATION DIVISION	
Printed Name: Denise Menoud	Signed By: <i>[Signature]</i> Approved by Environmental Specialist:	
Title: Field Admin Support	Approval Date: 9/22/16	Expiration Date: N/A
E-mail Address: Denise.Menoud@dvn.com	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines Attached <input type="checkbox"/>	
Date: 4/29/2016 Phone: 575-746-5544	SUBMIT REMEDIATION PROPOSAL NO LATER THAN: 10/26/16	

* Attach Additional Sheets If Necessary

2RP-3899