

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141

Revised August 8, 2011

SEP 29 2016

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

DAB1027739696 OPERATOR ☐ Initial Report ☒ Final Report

Name of Company OXY USA WTP LP	Contact Jennifer Duarte
Address PO BOX 4294; HOUSTON, TX 77210	Telephone No. 713-513-6640
Facility Name STATE CV COM #1	Facility Type WELL

Surface Owner	Mineral Owner	API No. 30-015-21927
---------------	---------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
E	16	20S	28E	1980	NORTH	760	WEST	EDDY

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release GAS - FLARE	Volume of Release 6998 MCF	Volume Recovered 0
Source of Release GAS - FLARE	Date and Hour of Occurrence 07/28/2016 - BEGAN 08/12/2016 - END	Date and Hour of Discovery
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Flaring due to restart gas lift compressor.

Describe Area Affected and Cleanup Action Taken.*

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Jennifer Hudgens</u>	OIL CONSERVATION DIVISION	
Printed Name: JENNIFER HUDGENS	Signed By: <u>Mike Brannan</u> Approved by Environmental Specialist	
Title: ENVIRONMENTAL SPECIALIST	Approval Date: <u>10/31/16</u>	Expiration Date: <u>N/A</u>
E-mail Address: jennifer_duarte@oxy.com	Conditions of Approval: <u>FINAL</u>	Attached <input type="checkbox"/>
Date: 09/29/2016	Phone: 713-513-6640	

* Attach Additional Sheets If Necessary

*2RP-3550

Bratcher, Mike, EMNRD

From: Jennifer_Duarte@oxy.com
Sent: Thursday, September 29, 2016 12:37 PM
To: Bratcher, Mike, EMNRD
Subject: Flaring C141S
Attachments: Scanned from a Xerox Multifunction Device001.pdf; Scanned from a Xerox Multifunction Device002.pdf

Importance: High

Please see the attached notices for flaring. Should you have any questions or need any additional information, please let me know.

Thank you,
Jennifer Hudgens
Environmental Specialist
713-513-6640