

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

NM OIL CONSERVATION

ARTESTA DISTRICT

OCT 07 2016

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
RECEIVED accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1628631827

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: COG Operating LLC 229137	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: SUPERFORTRESS 29 FEDERAL #003H	Facility Type: Battery

Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-38642
------------------------	------------------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
C	29	19S	31E	330	North	2200	West	Eddy

32.6377373,-103.8928909

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 10 bbls Produced Water	Volume Recovered: 7 bbls Produced Water
Source of Release:	Date and Hour of Occurrence: 9/30/2016 unknown	Date and Hour of Discovery: 9/30/2016 12:01 PM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*



This release was caused by a hole in a check valve. The damaged check valve was replaced to prevent incident from occurring again.

Describe Area Affected and Cleanup Action Taken.*

This battery occurred within a lined facility. Vacuum trucks were immediately dispatched to recover standing fluid and the contaminated gravel has been replaced with fresh gravel. Concho will have the spill site inspected for any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: 	Approved by Environmental Specialist: 	
Printed Name: Dakota Neel	Approval Date: 10/11/16	Expiration Date: NA
Title: Environmental Coordinator	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines <input type="checkbox"/>	
E-mail Address: dneel2@concho.com	SUBMIT REMEDIATION PROPOSAL NO	
Date: October 7, 2016	Phone: 575-748-6933	LATER THAN: 11/12/16

* Attach Additional Sheets If Necessary

ARP-3933

Patterson, Heather, EMNRD

From: Dakota Neel <DNeel2@concho.com>
Sent: Friday, October 07, 2016 9:34 AM
To: Patterson, Heather, EMNRD; James_Amos@blm.gov; Bratcher, Mike, EMNRD; stucker@blm.gov
Cc: Robert McNeill
Subject: (C-141 Initial) Superfortress 29 Feddeal #003H (30-015-38642)
Attachments: 9-30-2016 Superfortress 29 Federal #003H (30-015-38642).pdf

Mr. Bratcher/Ms. Tucker,

Attached is a C-141 for your consideration. If you have any additional questions please feel free to contact me.

Thank you,

Dakota Neel
Environmental Coordinator
COG Operating LLC
Cell: 432-215-2783
dneel2@concho.com

2407 Pecos Ave.
Artesia , NM 88210



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information herein, is prohibited. If you received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.