District II		f New Mexico s and Natural Resources	Form Revised Augus
111 S. First St., Artesia, NM 88210 District III		ervation Division	
1000 Rio Brazos Road, Aztec, NM 87410 District IV		th St. Francis Dr.	Submit I Copy to appropriate District (accordance with 19.15.29
1220 S. St. Francis Dr., Santa Fe, NM 87505		Fe, NM 87505	
R		on and Corrective Act	ion
NAB16287400		OPERATOR	Initial Report 🛛 Fina
Name of Company OXY USA INC		Contact	
	U1046	Jennifer Duarte	
Address PO BOX 4294; HOUSTON, TZ Facility Name CONOCO 7 STATE #1		Telephone No. 713-513-6640 Facility Type CTB	
Surface Owner	Mineral Owner	•	API No. 30-015-23174
· · · · · · · · · · · · · · · · · · ·		ON OF RELEASE	
Unit Letter Section Township Rang N 7 19S 29E	e Feet from the Nor 660 SOU		ast/West Line County VEST EDDY
	Latitude	Longitude	➡
	NATUR	E OF RELEASE	
Type of Release GAS - FLARE Source of Release GAS - FLARE		Volume of Release 286 MCF Date and Hour of Occurrence	Volume Recovered 0 Date and Hour of Discovery
		08/03/2016 - BEGAN	
Was Immediate Notice Given?		08/04/2016 - ENDED	
	No Not Require		
By Whom?		Date and Hour	
Was a Watercourse Reached?		If YES, Volume Impacting the	Watercourse.
•			
Describe Cause of Problem and Remedial Ac	tion Taken.*		· · · · · · · · · · · · · · · · · · ·
	· · ·	nnen causing gas to flare to t	anks and so out flare. Stopped a
OXY-Dump valve on the Vertical liqu	· · ·	open causing gas to flare to t	anks and go out flare. Stopped a
	· · ·	open causing gas to flare to t	anks and go out flare. Stopped a
OXY-Dump valve on the Vertical liqu repaired water dump controller.	id scrubber got stuck	open causing gas to flare to t	anks and go out flare. Stopped a
OXY-Dump valve on the Vertical liqu	id scrubber got stuck	open causing gas to flare to t	anks and go out flare. Stopped a
OXY-Dump valve on the Vertical liqu repaired water dump controller.	id scrubber got stuck	open causing gas to flare to t	anks and go out flare. Stopped a
OXY-Dump valve on the Vertical liqu repaired water dump controller. Describe Area Affected and Cleanup Action	id scrubber got stuck Taken.*		
OXY-Dump valve on the Vertical liqu repaired water dump controller. Describe Area Affected and Cleanup Action	id scrubber got stuck Taken.*	the best of my knowledge and und	rrstand that pursuant to NMOCD rules a
OXY-Dump valve on the Vertical liqu repaired water dump controller. Describe Area Affected and Cleanup Action I hereby certify that the information given ab regulations all operators are required to report	id scrubber got stuck Taken.* ove is true and complete to rt and/or file certain release	the best of my knowledge and und notifications and perform correctiv	ristand that pursuant to NMOCD rules a e actions for releases which may endang
OXY-Dump valve on the Vertical liqu repaired water dump controller. Describe Area Affected and Cleanup Action I hereby certify that the information given ab regulations all operators are required to repor public health or the environment. The accept	id scrubber got stuck Taken.* ove is true and complete to rt and/or file certain release tance of a C-141 report by	the best of my knowledge and und notifications and perform correctiv the NMOCD marked as "Final Repo	rrstand that pursuant to NMOCD rules a e actions for releases which may endang ort" does not relieve the operator of liabi
OXY-Dump valve on the Vertical liqu repaired water dump controller. Describe Area Affected and Cleanup Action I hereby certify that the information given ab regulations all operators are required to repor public health or the environment. The accept should their operations have failed to adequa or the environment. In addition, NMOCD ac	id scrubber got stuck Taken.* ove is true and complete to n and/or file certain release tance of a C-141 report by tely investigate and remedi tocptance of a C-141 report	the best of my knowledge and und notifications and perform correctiv the NMOCD marked as "Final Repu ate contamination that pose a threat	rrstand that pursuant to NMOCD rules a e actions for releases which may endang ort" does not relieve the operator of liabi to ground water, surface water, human l
OXY-Dump valve on the Vertical liqu repaired water dump controller. Describe Area Affected and Cleanup Action I hereby certify that the information given ab regulations all operators are required to repor public health or the environment. The accept should their operations have failed to adequa	id scrubber got stuck Taken.* ove is true and complete to n and/or file certain release tance of a C-141 report by tely investigate and remedi tocptance of a C-141 report	the best of my knowledge and under notifications and perform corrective the NMOCD marked as "Final Reputer ate contamination that pose a threat does not relieve the operator of rest	erstand that pursuant to NMOCD rules a e actions for releases which may endang ort" does not relieve the operator of liabi to ground water, surface water, human l ponsibility for compliance with any othe
OXY-Dump valve on the Vertical liqu repaired water dump controller. Describe Area Affected and Cleanup Action I hereby certify that the information given ab regulations all operators are required to repor public health or the environment. The accept should their operations have falled to adequa or the environment. In addition, NMOCD ac federal, state, or local laws and/or regulations	id scrubber got stuck Taken.* ove is true and complete to n and/or file certain release tance of a C-141 report by tely investigate and remedi tocptance of a C-141 report	the best of my knowledge and under notifications and perform correctiv the NMOCD marked as "Final Repo ate contamination that pose a threat does not relieve the operator of res	rrstand that pursuant to NMOCD rules a e actions for releases which may endang ort" does not relieve the operator of liabi to ground water, surface water, human l
OXY-Dump valve on the Vertical liqu repaired water dump controller. Describe Area Affected and Cleanup Action I hereby certify that the information given ab regulations all operators are required to repor public health or the environment. The accept should their operations have failed to adequa or the environment. In addition, NMOCD ac	id scrubber got stuck Taken.* ove is true and complete to n and/or file certain release tance of a C-141 report by tely investigate and remedi tocptance of a C-141 report	the best of my knowledge and under notifications and perform correctiv the NMOCD marked as "Final Repo ate contamination that pose a threat does not relieve the operator of res OIL CONSE	erstand that pursuant to NMOCD rules a e actions for releases which may endang ort" does not relieve the operator of liabi to ground water, surface water, human l ponsibility for compliance with any othe IRVATION DIVISION
OXY-Dump valve on the Vertical liqu repaired water dump controller. Describe Area Affected and Cleanup Action I hereby certify that the information given ab regulations all operators are required to repor public health or the environment. The accept should their operations have falled to adequa or the environment. In addition, NMOCD ac federal, state, or local laws and/or regulations	id scrubber got stuck Taken.* ove is true and complete to n and/or file certain release tance of a C-141 report by tely investigate and remedi tocptance of a C-141 report	the best of my knowledge and under notifications and perform correctiv the NMOCD marked as "Final Repo ate contamination that pose a threat does not relieve the operator of res	erstand that pursuant to NMOCD rules a e actions for releases which may endang ort" does not relieve the operator of liabi to ground water, surface water, human l ponsibility for compliance with any othe IRVATION DIVISION
OXY-Dump valve on the Vertical liqu repaired water dump controller. Describe Area Affected and Cleanup Action I hereby certify that the information given ab regulations all operators are required to repor public health or the environment. The accept should their operations have falled to adequa or the environment. In addition, NMOCD ac federal, state, or local laws and/or regulations Signature:	id scrubber got stuck Taken.* ove is true and complete to n and/or file certain release tance of a C-141 report by tely investigate and remedi tocptance of a C-141 report	the best of my knowledge and under notifications and perform correctiv the NMOCD marked as "Final Repo ate contamination that pose a threat does not relieve the operator of res OIL CONSE	erstand that pursuant to NMOCD rules a e actions for releases which may endang ort" does not relieve the operator of liabi to ground water, surface water, human l ponsibility for compliance with any othe IRVATION DIVISION
OXY-Dump valve on the Vertical liqu repaired water dump controller. Describe Area Affected and Cleanup Action I hereby certify that the information given ab regulations all operators are required to repor- public health or the environment. The accept should their operations have falled to adequa or the environment. In addition, NMOCD ac federal, state, or local laws and/or regulations Signature:	id scrubber got stuck Taken.* ove is true and complete to n and/or file certain release tance of a C-141 report by tely investigate and remedi tocptance of a C-141 report	the best of my knowledge and undanotifications and perform corrective the NMOCD marked as "Final Repute ate contamination that pose a threat does not relieve the operator of rest OIL CONSE Approved by Environmental Spect	erstand that pursuant to NMOCD rules a e actions for releases which may endang rt" does not relieve the operator of liabi to ground water, surface water, human l ponsibility for compliance with any othe RVATION DIVISION With Bammuse tafist:
OXY-Dump valve on the Vertical liqu repaired water dump controller. Describe Area Affected and Cleanup Action I hereby certify that the information given ab regulations all operators are required to repor- public health or the environment. The accept should their operations have falled to adequa or the environment. In addition, NMOCD ac federal, state, or local laws and/or regulations Signature: Printed Name: JENNIFER DUARTE Title: ENVIRONMENTAL SPECIALIST E-mail Address: jennifer_duarte@oxy.com	id scrubber got stuck Taken.* ove is true and complete to n and/or file certain release tance of a C-141 report by tely investigate and remedi tocptance of a C-141 report	the best of my knowledge and under notifications and perform corrective the NMOCD marked as "Final Report ate contamination that pose a threat does not relieve the operator of rest <u>OIL CONSE</u> Approved by Environmental Spect	erstand that pursuant to NMOCD rules a e actions for releases which may endang ort" does not relieve the operator of liabi to ground water, surface water, human I ponsibility for compliance with any othe iRVATION DIVISION which Banance taffst: 2 Expiration Date: NIA