

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

NM OIL CONSERVATION State of New Mexico
ARTESIA DISTRICT Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

OCT 05 2016 Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company LINN Energy	Contact EL Gonzales
Address 2130 W. Bender Blvd. Hobbs, NM 88240	Telephone No. 575-738-1739
Facility Name H E West-B #27 (Keel West Water Flood)	Facility Type Injection <i>E-File #668</i>

Surface Owner BLM	Mineral Owner	API No. 30-015-05074
-------------------	---------------	----------------------

LOCATION OF RELEASE

Unit Letter N	Section 4	Township 17S	Range 31E	Feet from the 660'	North/South Line South	Feet from the 1980'	East/West Line West	County Eddy
------------------	--------------	-----------------	--------------	-----------------------	---------------------------	------------------------	------------------------	----------------

Latitude 32.8581161 Longitude -103.8769989

NATURE OF RELEASE



Type of Release Oil	Volume of Release 50 BBLS	Volume Recovered 30 BBLS
Source of Release Injection Line	Date and Hour of Occurrence Unknown	Date and Hour of Discovery 3/17/11
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? OCD- Mike Bratcher	
By Whom? Dennis Potter	Date and Hour 3/17/11	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken *
Injection Line Leaked. Fixed injection line leak

Describe Area Affected and Cleanup Action Taken.*
Inside containment. Picked up fluids
Remediation complete

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION		
Printed Name: E. L. Gonzales	Approved by Environmental Specialist: 		
Title: Production Supervisor	Approval Date: 10/14/16	Expiration Date: N/A	
E-mail Address: ELgonzales@linnenergy.com	Conditions of Approval: <i>Final</i>		Attached <input type="checkbox"/>
Date: 9/8/16	Phone: (575) 738-1739		

* Attach Additional Sheets If Necessary

22P-668