

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141
Revised August 8, 2011

NOV 08 2016

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1631455601

OPERATOR

Initial Report Final Report

Name of Company Devon Energy Production Company <i>U137</i>		Contact Matt Nettles, Production Foreman
Address 6488 Seven Rivers Hwy Artesia, NM 88210		Telephone No. 575.513.5767
Facility Name Harroun Trust 31 Fed Com 2H		Facility Type Oil Well
Surface Owner Federal	Mineral Owner Federal	API No 30-015-41963

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	31	23S	29E	330	FSL	1305	FWL	Eddy

Latitude: 32.2551956

Longitude: -104.0280991

NATURE OF RELEASE

Type of Release Oil	Volume of Release 5BBLs	Volume Recovered 5BBLs, 5BBLs Rainwater
Source of Release Circulating drain pot	Date and Hour of Occurrence 11/3/2016 @ 2:30AM	Date and Hour of Discovery 11/3/2016 @ 2:30AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? OCD-Mike Bratcher BLM-Shelly Tucker	
By Whom? Leonard Aguilar, Assistant Foreman	Date and Hour 11/3/2016 @ 10:10AM 11/3/2016 @ 10:12AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse N/A	

If a Watercourse was Impacted, Describe Fully.*
N/A

Describe Cause of Problem and Remedial Action Taken.*

The suction bleeder line was open and the discharge valve was closed which resulted in the circulating drain pot filling and overflowing into the surrounding lined containment. The line that had been open was closed to prevent further release.

Describe Area Affected and Cleanup Action Taken.*

Approximately 5BBLs of oil was released from the circulating drain pot and overflowed into the surrounding lined containment. The release originated between the first produced water storage tank and the containment wall located on the northeast side of location. All fluid stayed in lined containment, the liner was checked for holes, no holes found in liner. 5BBLs oil and 5BBLs of rainwater were recovered via vacuum truck. No further action required.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Dana DeLaRosa</i>	OIL CONSERVATION DIVISION	
Printed Name: Dana DeLaRosa	Signed By <i>Mike Bratcher</i>	
Title: Field Admin Support	Approved by Environmental Specialist:	Approval Date: <i>11/11/16</i> Expiration Date: <i>N/A</i>
E-mail Address: <i>dana.delarosa@dvn.com</i>	Conditions of Approval: <i>FINAL</i>	Attached <input checked="" type="checkbox"/>
Date: 11/8/2016 Phone: 575.746.5594		

* Attach Additional Sheets If Necessary

ARP-3978

Bratcher, Mike, EMNRD

From: DeLaRosa, Dana <Dana.DeLaRosa@dvn.com>
Sent: Tuesday, November 08, 2016 1:32 PM
To: Bratcher, Mike, EMNRD
Subject: Harroun Trust 31 Fed Com 2H_5BBL Oil Release_11.3.2016
Attachments: Harroun Trust 31 FedCom 2H_5BBL Oil_11.3.2016_Initial & Final C141.doc; Harroun Trust 31 Fed Com 2H_5BBL Oil_11.3.2016_GIS Image.pdf

Good afternoon,

Attached is the Initial & Final C141 and GIS Image for the 5BBL Oil release that occurred on 11.3.2016. The red dot on the GIS Image represents the approximate origin of release.

Thank you and have a great day,

Dana DeLaRosa

Field Admin Support
Production
B-Schedule



Devon Energy Corporation
PO Box 250
Artesia, NM 88211
575-746-5594

Confidentiality Warning: This message and any attachments are intended only for the use of the intended recipient(s), are confidential, and may be privileged. If you are not the intended recipient, you are hereby notified that any review, retransmission, conversion to hard copy, copying, circulation or other use of all or any portion of this message and any attachments is strictly prohibited. If you are not the intended recipient, please notify the sender immediately by return e-mail, and delete this message and any attachments from your system.