

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

NM OIL CONSERVATION

ARTESIA DISTRICT

NOV 15 2016

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.
RECEIVED

Release Notification and Corrective Action

NAME NAB1632133942 **OPERATOR** ☒ Initial Report ☐ Final Report

Name of Company Devon Energy Production Company	Contact Matt Nettles, Production Foreman	
Address 6488 Seven Rivers Hwy Artesia, NM 88210	Telephone No. 575-513-5767	
Facility Name Cochiti 28 Federal #1	Facility Type Salt Water Disposal	
Surface Owner Federal	Mineral Owner Federal	API No 30-015-30113

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
E	28	23S	29E	1980	North	660	West	Eddy

Latitude: N 32.2777977 **Longitude:** W -103.996315

NATURE OF RELEASE

8 recovered

Type of Release Produced water	Volume of Release 8 BBLs	Volume Recovered 70 BBLs
Source of Release Triplex plunger pump	Date and Hour of Occurrence 11/8/2016 @ 11:30pm	Date and Hour of Discovery 11/8/2016 @ 11:30pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? OCD-Mike Bratcher BLM-Jim Amos	
By Whom? Hub Perry, Night Production Foreman	Date and Hour OCD- 11/9/16 @ 8:44pm BLM- 11/9/16 @ 8:27pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse N/A	

If a Watercourse was Impacted, Describe Fully.* N/A

Describe Cause of Problem and Remedial Action Taken.*

The seal on the Triplex plunger pump became loose resulting in a release of 8 BBLs produced water. The suction lines were isolated immediately to prevent further release. The Triplex plunger pump has been repaired.

Describe Area Affected and Cleanup Action Taken.*

8 BBLs produced water was released from the Triplex plunger pump onto the ground. The area affected was on the Southwestern portion of the pad. All released produced water was contained on pad. None of the released fluid left pad. Vacuum truck recovered approximately 8 BBLs of produced water and 62 BBLs of rain water on location. Environmental agency will be contacted for remediation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Sarah Gallegos-Troublefield	OIL CONSERVATION DIVISION	
Printed Name: Sarah Gallegos-Troublefield	Signed By <i>[Signature]</i>	
Title: Field Admin Support	Approval Date: 11/16/16	Expiration Date: N/A
E-mail Address: Sarah.Gallegos-Troublefield@dmv.com	Conditions of Approval:	Attached <input checked="" type="checkbox"/>
Date: 11/15/2016 Phone: 575.748.1864		

* Attach Additional Sheets If Necessary

2RP-3995

Bratcher, Mike, EMNRD

From: Gallegos-Troublefield, Sarah <Sarah.Gallegos-Troublefield@dvn.com>
Sent: Tuesday, November 15, 2016 9:12 AM
To: jamos@blm.gov; Tucker, Shelly; Patterson, Heather, EMNRD; Bratcher, Mike, EMNRD
Cc: Fulks, Brett
Subject: Cochiti 28 Federal #1_8 BBLS PW_11-8-2016_Initial C-141
Attachments: Cochiti 28 Federal 1_8 BBLS PW_11-8-2016_GIS Image.pdf; Cochiti 28 Federal 1_8 BBLS PW_11-8-2016_Initial C-141.doc

Good Morning,

Please find attached the Initial C-141 and the GIS Image of the Cochiti 28 Federal #1 release of 8 BBLS PW that occurred on 11/8/2016. Please be advised that the blue dot on the GIS Image represents the approximate location of the origin of release. Please contact me with any questions you may have.

Thank you very much and have a wonderful and safe day!

Respectfully,

Sarah Gallegos-Troublefield
Field Admin Support
Production

Devon Energy Corporation
P.O. Box 250
Artesia, NM 88211
575 748 1864 Direct Line



Confidentiality Warning: This message and any attachments are intended only for the use of the intended recipient(s), are confidential, and may be privileged. If you are not the intended recipient, you are hereby notified that any review, retransmission, conversion to hard copy, copying, circulation or other use of all or any portion of this message and any attachments is strictly prohibited. If you are not the intended recipient, please notify the sender immediately by return e-mail, and delete this message and any attachments from your system.