

NM OIL CONSERVATION

ARTESIA DISTRICT

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NOV 14 2016

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

OPERATOR ☐ Initial Report ☒ Final Report

Name of Company OXY USA INC **Contact** Jennifer Duarte

Address PO BOX 4294; HOUSTON, TX 77210 **Telephone No.** 713-513-6640

Facility Name CEDAR CANYON CDP **Facility Type** CDP



Surface Owner **Mineral Owner** **API No.** 30-015-34997

LOCATION OF RELEASE

| Unit Letter | Section | Township | Range | Feet from the | North/South Line | Feet from the | East/West Line | County |
|-------------|---------|----------|-------|---------------|------------------|---------------|----------------|--------|
| P | 9 | 24S | 29E | | | | | |

Latitude _____ Longitude _____

NATURE OF RELEASE

| | | |
|--|--|---|
| Type of Release GAS - FLARE | Volume of Release 389 MCF | Volume Recovered 0 |
| Source of Release GAS - FLARE | Date and Hour of Occurrence 11/11/2016 - BEGAN | Date and Hour of Discovery |
| Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required | If YES, To Whom? | |
| By Whom? | Date and Hour | |
| Was a Watercourse Reached? <input type="checkbox"/> Yes <input type="checkbox"/> No | If YES, Volume Impacting the Watercourse. | |
| If a Watercourse was Impacted, Describe Fully.* | | |
| Describe Cause of Problem and Remedial Action Taken.* Enterprise compressor issues. | | |
| Describe Area Affected and Cleanup Action Taken.* | | |
| I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. | | |
| Signature:  | OIL CONSERVATION DIVISION | |
| Printed Name: JENNIFER HUGGENS | Approved by Environmental Specialist:  | |
| Title: ENVIRONMENTAL SPECIALIST | Approval Date: 11/22/16 | Expiration Date: N/A |
| E-mail Address: jennifer_duarte@oxy.com | Conditions of Approval: FINAL | Attached <input checked="" type="checkbox"/> |
| Date: 11/14/2016 Phone: 713-513-6640 | | |

* Attach Additional Sheets If Necessary

2 RP-3544
Orig. final 3/1/16

Bratcher, Mike, EMNRD

From: Jennifer_Hudgens@oxy.com
Sent: Monday, November 14, 2016 2:31 PM
To: Bratcher, Mike, EMNRD
Subject: C141s for Flaring
Attachments: Scanned from a Xerox Multifunction Device001.pdf; Scanned from a Xerox Multifunction Device002.pdf; Scanned from a Xerox Multifunction Device003.pdf

Please see the attached C141s for flaring. Should you need any additional information, please let me know.

Thank you,
Jennifer Hudgens
Environmental Specialist
713-513-6640