NM OIL CONSERVATION ARTESIA DISTRICT

1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV

State of New Mexico **Energy Minerals and Natural Resources**

NOV 2 6 2016

Form C-141 Revised August 8, 2011

Oil Conservation Division

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

1220 South St. Francis Dr. 1220 S. St. Francis Dr., Santa Fe, NM 87505 Santa Fe, NM 87505 Release Notification and Corrective Action OPERATOR Chevron USA Initial Report ☐ Final Report Name of Company Contact Josepha DeLeon 79706 Address 6301 Deauville Blvd, Midland, TX Telephone No. 575-263-0424 Facility Name Nereid 1 Federal No. 1H Facility Type: Oil Well Surface Owner BLM Mineral Owner API No. 30-005-29145-00-S1 LOCATION OF RELEASE Unit Letter Range Section Township Feet from the North/South Line Feet from the East/West Line County 15S 31E 660 South Chavez Latitude Longitude NATURE OF RELEASE Type of Release: Oil & Water Volume of Release 36 bbl of oil Volume Recovered 36 bbl of oil and 53 and 53 bbl of water bbl of water Source of Release: Heater Treater Date and Hour of Occurrence Date and Hour of Discovery 11/13/2016 08:00 AM 11/13/2016 08:00 AM Was Immediate Notice Given? If YES, To Whom? Heather Patterson, NMOCD and Harley Davis, BLM By Whom? Josepha DeLeon Date and Hour 11/14/2016 07:00 AM Was a Watercourse Reached? If YES, Volume Impacting the Watercourse. ☐ Yes ☒ No If a Watercourse was Impacted, Describe Fully.* Not Applicable Describe Cause of Problem and Remedial Action Taken.* Heater treater. Spill was into the secondary containment and all 89 barrels of fluid were recovered. Describe Area Affected and Cleanup Action Taken.* A vacuum truck was called to the location and was able to recover 89 barrels of the fluid from secondary metal, plastic lined containment. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. **OIL CONSERVATION DIVISION** Signature: Approved by Environmental Specialist: Printed Name: Josepha DeLeon Expiration Date: Title: HES Compliance Support - Environmental Approval Date:

Conditions of Approval:

Attach Additional Sheets If Necessary

Phone: 575-263-0424

E-mail Address: jdxd@chevron.com

Date: 11/22/2016

Attached

INAL

Patterson, Heather, EMNRD

From:

DeLeon, Josepha <JDXD@chevron.com>

Sent:

Saturday, November 26, 2016 11:22 PM

To:

Patterson, Heather, EMNRD; hcdavis@blm.gov

Cc:

Barakat, Eli; Davis, Allen; Debeyssey, Svetlana

Subject: Attachments: C-141 - Nereid 1 Federal No. 1H

Nereid 1 Federal No. 1H - C141.pdf

Attached is the C-141 for the spill that occurred at the Nereid 1 Federal No. 1H.

If you need further information do not hesitate to contact me.

Josie DeLeon, HES Specialist -

Compliance Support - Environmental

Chevron - MCBU

(SE NM Areas, Dollarhide, Eunice, Hobbs and Vacuum)

1616 W. Bender Blvd. Hobbs, NM 88240 575-263-0424

432-425-1528 - cell

idxd@chevron.com

https://www.chevroncontractorsafety.com/contractormcbu/ - CHESM Contractor Website

6 Green/Red – The Doing Thinker