District I 1625 N. French District II 811 S. First St					ate of an	New Mex and Natura	ico l Resources			Form C-141 Revised August 8, 2011		
District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 Sou						ervation Division th St. Francis Dr.			Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.			
1220 S. St. Francis Dr., Santa Fe, NM 87 Santa Fe, NM 87505 PAB1034130488 Release Notification and Corrective Action												
		36647				OPERA]				al Report 🔲 Final Repor		
Name of Company HOLLY ENERGY PARTNERS						Contact MELANIE ISENBERG						
Address 16		IN ST NSDALL LII			Telephone No. 214-605-8303 Facility Type CRUDE OIL PIPELINE							
		15DALL LI										
BLM	Surface Owner Mineral Owne									API No.		
LOCATION OF RELEASE												
Unit LetterSectionTownshipRangeFeet2617S29			Feet from the			Feet from the	East/West Line		County EDDY			
Latitude <u>32.8042</u> Longitude <u>-104.515</u>												
NATURE OF RELEASE												
Type of Rele		E			Release 26 Barro			Recovered 0				
Source of Release UNDERGROUND PIPELINE						UNKNOV	VN	Date and Hour of Discovery 11/17/2016 1420				
Was Immediate Notice Given?						If YES, To Whom? NMOCD AND NMED						
By Whom? MELANIE ISENBERG						Date and Hour 5/4/2016 NOTIFICATIONS COMPLETED TO BOTH AGENCIES BY 1520						
Was a Watercourse Reached?						If YES, Volume Impacting the Watercourse.						
If a Watercou N/A	urse was Im	pacted, Descri	ibe Fully.'	K		l						
N/A Describe Cause of Problem and Remedial Action Taken.* A PIPELINE LEAK COMING FROM THE LINE RUNNING FROM THE RJU SOUTH TANK BATTERY INTO THE BARNSDALL LINE. LINE WAS SHUT DOWN AND CREWS WERE DISPATCHED. LEAK WAS FOUND AND REPAIRS ON LINE WERE COMPLETED BY 11/18/16. ALL SOILS REMOVED TO ACCESS PIPELINE WERE REMOVED AND PLACED ON PLASTIC.												
	Describe Area Affected and Cleanup Action Taken.* THE AREA AFFECTED IS LOCATED OFF OF AN ACCESS DIRT ROAD THAT IS APPROXIMATELY A MILE SE OF BARNSDALL STATION. ESTIMATED AMOUNT OF SPILL IS 26 BARRELS. LEAK WAS											
LOCATED AND REPAIR TO LINE WAS MADE. CONTAMINATED SOIL THAT WAS REMOVED FROM AREA WAS PLACED ON PLASTIC TILL IT CAN EITHER BE REMEDIATED OR DISPOSED OF. SITE IS CURRENTLY BEING DELINEATED. WORK PLAN WILL BE SUBMITTED ONCE SITE IS DELINEATED. ATTACHED IS 2 MAPS DEPICTING LEAK LOCATION.												
I hereby certi regulations a public health should their or the enviro	ify that the i ll operators or the enviro operations h nment. In a	information gi are required to ronment. The nave failed to a	ven above o report ar acceptance adequately OCD accept	e is true and comp id/or file certain re- ce of a C-141 repor- investigate and re-	lete to the elease not ort by the emediate	he best of my otifications an e NMOCD m e contaminati	knowledge and u nd perform correc arked as "Final R on that pose a thr e the operator of	ndersta ctive act eport" c eat to g respons	nd that purs ions for rel- loes not rel round wate ibility for c	suant to NMOCD rules and eases which may endanger ieve the operator of liability r, surface water, human health ompliance with any other		
						OIL CONSERVATION DIVISION						
Signature: Melanie ISENDERC						Approved by Environmental speciation						
Printed Name: MELANIE ISENBERG Title: ENVIRONMENTAL ASSOCIATE						Approval Dat	illoolu	P	Expiration	Date: N/A		
E-mail Address: MELANIE.ISENBERG@HOLLYENERGY.COM						Conditions of Approval:			Attached 🔽			
Date: 11/22 * Attach Addi			: <u>21</u> 4-605 ary	-8303						2RP-4020		



