

NM OIL CONSERVATION
ARTESIA DISTRICT

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico DEC 14 2016
Energy Minerals and Natural Resources
Oil Conservation Division RECEIVED
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

NAB1635450906
NAB1635451113

Release Notification and Corrective Action

OPERATOR		<input checked="" type="checkbox"/> Initial Report	<input checked="" type="checkbox"/> Final Report
Name of Company: ETC Field Services 371183		Contact: Johnnie Bradford	
Address: 600 N. Marienfeld Street, Ste. 700		Telephone No. (432) 250-5542 (cell) (817) 302-9812 (off)	
Facility Name: California A		Facility Type: Pipeline	

Surface Owner:	Mineral Owner:	API No.
----------------	----------------	---------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	I	26S	30E	22.76	South	337.98	East	Eddy

Latitude 32.06468N Longitude 103.8422W

NATURE OF RELEASE



Type of Release: Gas Only	Volume of Release: 317.252 Mscf	Volume Recovered: 0
Source of Release: Pipeline	Date and Hour of Occurrence: 12/07/2016 11:30	Date and Hour of Discovery: 12/07/2016 11:30
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? N/A	
By Whom? N/A	Date and Hour: N/A	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. Watercourse was not affected.	

If a Watercourse was Impacted, Describe Fully.*
Watercourse was not affected.

Describe Cause of Problem and Remedial Action Taken.*
Due to external corrosion on a section of 16" pipeline developed a hole which released field natural gas. Following repairs, this pipeline was purged prior to returning to normal service.

Describe Area Affected and Cleanup Action Taken.*
Since this was a gas only release, there were no adverse effects to the surrounding area.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Johnnie Bradford	Signed By:  Approved by Environmental Specialist:	
Title: Sr. Environmental Specialist	Approval Date: 12/20/16	Expiration Date: N/A
E-mail Address: johnnie.bradford@energytransfer.com	Conditions of Approval: FINAL	Attached <input type="checkbox"/>
Date: 12/14/2016	Phone: (432) 250-5542	

* Attach Additional Sheets If Necessary

2RP-4036