District I 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

## NM OIL CONSERVATION

ARTESIA DISTRICT MAR 1 4 2017

Form C-141 Revised August 8, 2011

2RP4146

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

State of New Mexico

**Energy Minerals and Natural Resources** 

**RECEIVER** to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action													
NAB1709452602							<b>OPERATOR</b> Initial Report I Final Re					Final Report	
							Contact Blaise Campanella						
						Telephone No. 575-748-5488							
Facility Name Scottsdale Federal #3						Facility Type production well							
Surface Owner BLM Mineral Owner H							BLM API No. 30-015-25307						
LOCATION OF RELEASE													
Unit LetterSectionTownshipRangeFeet from theTownshipG2718s31e1850					North/S FNL				West Line County EL Eddy				
Latitude_32.3720606Longitude103.856527													
NATURE OF RELEASE													
Type of Rele										olume Recovered 0			
Source of Re	lease proc	uction tank				Date and Hour of Occurrence 3/1/2017			Date and Hour of Discovery 3/1/2017				
Was Immedia	ate Notice (					If YES, To Whom?							
🛛 Yes 🔲 No 🗌 Not Required													
By Whom? Blaise Campanella						Date and Hour 3/1/2017 11:40am							
Was a Watercourse Reached?							If YES, Volume Impacting the Watercourse.						
If a Watercourse was Impacted, Describe Fully.*													
Describe Cause of Problem and Remedial Action Taken.*													
The release occurred when oil from a failed tank was brought back to the wellbore to be stored in the casing of the well. The casing valve was then left open resulting in a release of crude oil. The area was scraped and the resulting spill pile is on location.													
		and Cleanup A											
The affected area covers the pad, partially into the lease road, and a small area that ran off into the pasture on the west side of location. The site will be evaluated and remediated as per an NMOCD approved work plan.													
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and													
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger													
public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health													
or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other													
federal, state, or local laws and/or regulations.													
							OIL CONSERVATION DIVISION						
Signature: Ire: Ann Dans													
Printed Name: Blaise Campanella							Approved by Environmental Specialist 1/4 Drastalest						
Title: Member/Manager						Approval Date: 31517 Expiration Date: NIA							
E-mail Address: judahoil@yahoo.com						Conditions o	- î	-	1	Attached	I 🗆		
Date: 3/14/17 Phone: 575-748-5488 SEP Attached													

\* Attach Additional Sheets If Necessary

Operator/Responsible Party,

It is the Division's obligation under both the Oil & Gas Act and Water Quality Act to provide for the protection of public health and the environment. Our regulations (19.15.29.11 NMAC) state the following,

The responsible person shall complete <u>division-approved corrective action</u> for releases that endanger public health or the environment. The responsible person shall address releases in accordance with a remediation plan submitted to and approved by the division or with an abatement plan submitted in accordance with 19.15.30 NMAC. [emphasis added]

Release characterization is the first phase of corrective action unless the release is ongoing or is of limited volume and all impacts can be immediately addressed. Proper and cost-effective remediation typically cannot occur without adequate characterization of the impacts of any release. Furthermore, the Division has the ability to impose reasonable conditions upon the efforts it oversees. As such, the Division is requiring a workplan for the characterization of impacts associated with this release be submitted to the OCD District 2 office in <u>ARTESIA</u> on or before 5/2/17. If and when the release characterization workplan is approved, there will be an associated deadline for submittal of the resultant investigation report. Modest extensions of time to these deadlines may be granted, but only with acceptable justification.

The goals of a characterization effort are: 1) determination of the lateral and vertical extents along with the magnitude of soil contamination. 2) determine if groundwater or surface waters have been impacted. 3) If groundwater or surface waters have been impacted, what are the extents and magnitude of that impact. 4) The characterization of any other adverse impacts that may have occurred (examples: impacts on vegetation, impacts on wildlife, air quality, loss of use of property, etc.). To meet these goals as quickly as possible, the following items must, at a minimum, be addressed in the release characterization workplan and subsequent reporting:

• Horizontal delineation of soil impacts in each of the four cardinal compass directions. Adsorbed soil contamination must be characterized for the following constituents using the associated laboratory methods: benzene, toluene, ethylbenzene, and total xylenes by either Method 8260 or 8021, total petroleum hydrocarbons by Method 8015 extended range (GRO+DRO+MRO; C<sub>6</sub> thru C<sub>36</sub>), and for chloride by Method 300. This is not an exclusive list of potential contaminants. Analyzed parameters should be modified based on the nature of the released substance(s). Soil sampling must be both within the impacted area and beyond.

• Vertical delineation of soil impacts. Adsorbed soil contamination must be characterized for the following constituents using the associated laboratory methods: benzene, toluene, ethylbenzene, and total xylenes by either Method 8260 or 8021, total petroleum hydrocarbons by Method 8015 extended range (GRO+DRO+MRO; C<sub>6</sub> thru C<sub>36</sub>), and for chloride by Method 300. As above, this is not an exclusive list of potential contaminants and can be modified. Vertical characterization samples should be taken at depth intervals no greater than five feet apart. Lithologic description of encountered soils must also be provided. At least ten vertical feet of soils with contaminant concentrations at or below these values must be demonstrated as existing above the water table.

• Nominal detection limits for field and laboratory analyses must be provided.

• Composite sampling is not generally allowed.

• Field screening and assessment techniques are acceptable (headspace, titration, EC [include algorithm for validation purposes], EM, etc.), but the sampling and assay procedures must be clearly defined. Copies of field notes are highly desirable. A statistically significant set of split samples must be submitted for confirmatory laboratory analysis, including the laterally farthest and vertically deepest sets of soil samples. Make sure there are at least two soil samples submitted

for laboratory analysis from each borehole or test pit (highest observed contamination and deepest depth investigated). Copies of the actual laboratory results must be provided including chain of custody documentation.

•Probable depth to shallowest protectable groundwater and lateral distance to nearest surface water. If there is an estimate of groundwater depth, the information used to arrive at that estimate must be provided. If there is a reasonable assumption that the depth to protectable water is 50 feet or less, the responsible party should anticipate the need for at least one groundwater monitoring well to be installed in the area of likely maximum contamination.

• If groundwater contamination is encountered, an additional investigation workplan may be required to determine the extents of that contamination. Groundwater and/or surface water samples, if any, must be analyzed by a competent laboratory for volatile organic hydrocarbons (typically Method 8260 full list), total dissolved solids, pH, major anions and cations including chloride and sulfate, dissolved iron, and dissolved manganese. The investigation workplan must provide the groundwater sampling method(s) and sample handling protocols. To the fullest extent possible, aqueous analyses must be undertaken using nominal method detection limits. As with the soil analyses, copies of the actual laboratory results must be provided including chain of custody documentation.

• Accurately scaled and well-drafted site maps must be provided providing the location of borings, test pits, monitoring wells, potentially impacted areas, and significant surface features including roads and site infrastructure that might limit either the release characterization or remedial efforts. Field sketches may be included in subsequent reporting, but should not be considered stand-alone documentation of the site's layout. Digital photographic documentation of the location and fieldwork is recommended, especially if unusual circumstances are encountered.

Nothing herein should be interpreted to preclude emergency response actions or to imply immediate remediation by removal cannot proceed as warranted. Nonetheless, characterization of impacts and confirmation of the effectiveness of remedial efforts must still be provided to the OCD before any release incident will be closed.

Jim Griswold OCD Environmental Bureau Chief 1220 South St. Francis Drive Santa Fe, New Mexico 87505 505-476-3465 jim.griswold@state.nm.us

## Bratcher, Mike, EMNRD

From:	Heather Patterson <heather.patterson@soudermiller.com></heather.patterson@soudermiller.com>
Sent:	Tuesday, March 14, 2017 3:33 PM
То:	Bratcher, Mike, EMNRD; Weaver, Crystal, EMNRD; Tucker, Shelly (stucker@blm.gov)
Cc:	Austin Weyant; judahoil@yahoo.com
Subject:	Scottsdale fed #3 initial C141
Attachments:	scottsdale fed 3 initial c141.pdf

Please find the attached initial C-141 for a 3/1/2017 release on the Scottsdale Fed #3.

Thank you,

Heather Patterson Staff Scientist

Corporate Registrations: AZ Engineering/Geology/Surveying Firm (14070), SD Surveying Firm (C-7436), TX Engineering Firm (8877), TX Geology Firm (50254), TX PST CAPM (CS-0000051), TX Surveying Firm (10162200), WY Engineering/Surveying Firm (S-1704)



Souder, Miller & Associates Engineering ♦ Environmental ♦ Surveying 201 Halagueno St Carlsbad, NM 88220 www.soudermiller.com (575)200-5343 (mobile)



Notice of Confidentiality and Privileged Status: This electronic mail message, including all attachments, is for the sole use of the intended recipient(s) and may contain confidential and/or privileged information or otherwise may be protected from disclosure. Any unauthorized review, use, disclosure, distribution or actions which rely on the contents of this information is prohibited. If you are not the intended recipient, please contact the sender and delete the message and any attachments/s from your system.

Statement on Viruses and Harmful Software: While the message and attachment(s) have been scanned with anti-virus software, SMA does not guarantee that this message or any attachment(s) is free of computer viruses or other harmful software. SMA does not accept liability for any damages caused by any computer virus or other harmful software transmitted herewith.