

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

NM OIL CONSERVATION  
ARTESIA DISTRICT

MAR 07 2017

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB17M336310

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company: Mewbourne Oil Company	14744	Contact: Zack Thomas
Address: PO Box 5270 Hobbs NM 88241		Telephone No. 575-393-5905
Facility Name: Quick Draw 10 G #1 Battery		Facility Type: Producing Oil Well

Surface Owner: Private	Mineral Owner:	API No. 30-015-36500
------------------------	----------------	----------------------

LOCATION OF RELEASE

Unit Letter G	Section 10	Township 20S	Range 25E	Feet from the 2310'	North/South Line North	Feet from the 1650'	East/West Line East	County Eddy
------------------	---------------	-----------------	--------------	------------------------	---------------------------	------------------------	------------------------	----------------

Latitude 32.5888901 Longitude -103.4694977

NATURE OF RELEASE

Type of Release: Oil	Volume of Release: N/A overspray	Volume Recovered:
Source of Release: Poly Flow Line	Date and Hour of Occurrence 3-6-17	Date and Hour of Discovery 3-6-17 10:00 am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

Poly flow line failure. Well was shut-in to stop release.

Describe Area Affected and Cleanup Action Taken.\*

Affected area- 100' x 200' area North of tank battery. Micro blaze affected area.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Z. Thomas</u>	OIL CONSERVATION DIVISION	
Printed Name: Zack Thomas	Approved by Environmental Specialist <u>[Signature]</u>	
Title: Environmental Rep.	Approval Date: <u>4/3/17</u>	Expiration Date: <u>N/A</u>
E-mail Address: zthomas@mewbourne.com	Conditions of Approval: <u>FINAL</u>	Attached <input type="checkbox"/>
Date: 3-7-17	Phone: 575-602-2188	

\* Attach Additional Sheets If Necessary

2RP-4156

## Bratcher, Mike, EMNRD

---

**From:** Zack Thomas <zthomas@mewbourne.com>  
**Sent:** Tuesday, March 7, 2017 4:00 PM  
**To:** Bratcher, Mike, EMNRD  
**Subject:** Quick Draw 10 G #1 Battery  
**Attachments:** C141- Quick Draw 10 G #1 Battery (3-6-17) Initial&Final.pdf; IMG\_0092.JPG; IMG\_0093.JPG



**Zack Thomas**  
Environmental Rep.  
Mewbourne Oil Company  
PO Box 5270  
Hobbs, NM 88241 US

Phone: (575) 393-5905 | Fax: (575) 397-6252  
(575) 602-2188  
Email: [zthomas@mewbourne.com](mailto:zthomas@mewbourne.com)



**MEWBOURNE**  
**OIL COMPANY**