

NM OIL CONSERVATION

ARTESIA DISTRICT

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

MAY 12 2017

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1715654915

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company	Devon Energy Production Company	Contact	Matt Nettles, Production Foreman
Address	6488 Seven Rivers Hwy Artesia, NM 88210	Telephone No.	575-513-5767
Facility Name	Cotton Draw Unit 84	Facility Type	Salt Water Disposal

Surface Owner State	Mineral Owner State	API No	30-015-29728
---------------------	---------------------	--------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
1	2	25S	31E	2615	FSL	1160	FEL	Eddy

Latitude: 32.1592751

Longitude: -103.7438736

NATURE OF RELEASE

Type of Release	Volume of Release	Volume Recovered
Produced Water	32BBLS	32BBLS
Source of Release	Date and Hour of Occurrence	Date and Hour of Discovery
Filter Pot	5-1-2017 @ 3:55AM	5/1/2017 @ 3:55AM
Was Immediate Notice Given?	If YES, To Whom?	
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	BLM-Shelly Tucker OCD-Olivia Yu	
By Whom?	Date and Hour	
David Simmons, Assistant Production Foreman	BLM-5/1/2017 @ 4:20AM OCD-5/1/2017 @ 4:15AM	
Was a Watercourse Reached?	If YES, Volume Impacting the Watercourse	
<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	N/A	

If a Watercourse was Impacted, Describe Fully.*
N/A

Describe Cause of Problem and Remedial Action Taken.*

A filter pot ruptured an O-ring causing a release of 32 BBLS PW inside of the containment. The filter pot was isolated to prevent any further release from occurring. Repairs will be made to the equipment.

Describe Area Affected and Cleanup Action Taken.*

Approximately 32bbls produced water was released inside the lined containment. All 32BBLS of released produced water remained in the containment and was recovered back to the tanks through a sump pump at the facility. The containment and liner were visually inspected and placed back into service.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Dana DelaRosa	OIL CONSERVATION DIVISION	
Printed Name: Dana DelaRosa	Signed By: <i>[Signature]</i>	
Title: Field Admin Support	Approved by Environmental Specialist:	Approval Date: 6/5/17
E-mail Address: Dana.Delarosa@dm.com	Expiration Date: N/A	Conditions of Approval: FINAL
Date: Phone: 575.74.5594	Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

New forms can be found in the
New Mexico State Website in forms:
[http://www.emnrd.state.nm.us/
OCD/forms.html](http://www.emnrd.state.nm.us/OCD/forms.html)

APP-4235

Bratcher, Mike, EMNRD

From: Yu, Olivia, EMNRD
Sent: Friday, May 12, 2017 2:39 PM
To: Bratcher, Mike, EMNRD; Weaver, Crystal, EMNRD
Subject: FW: Cotton Draw Unit 84_32 BBLS PW_Intial C141_5.1.2017
Attachments: Cotton Draw Unit 84_32 BBLS PW release_ Initial C-141_5.1.2017.doc; Cotton Draw Unit 84_32BBLS PW_5.1.2017_GIS Image.pdf

Looks like another one of yours...

From: DeLaRosa, Dana [mailto:Dana.DeLaRosa@dvn.com]
Sent: Thursday, May 11, 2017 10:40 AM
To: Yu, Olivia, EMNRD <Olivia.Yu@state.nm.us>; agroves@slo.state.nm.us
Cc: Shoemaker, Mike <Mike.Shoemaker@dvn.com>; Fulks, Brett <Brett.Fulks@dvn.com>
Subject: Cotton Draw Unit 84_32 BBLS PW_Intial C141_5.1.2017

Good Morning,

Attached is the Initial C141 and GIS Image for the 32 BBL PW release that occurred on 5.1.2017. The red dot on the GIS Image represents the approximate origin of release.

Thank you and have a great day,

Dana DeLaRosa

Field Admin Support
Production
B-Schedule

Devon Energy Corporation
PO Box 250
Artesia, NM 88211
575 746 5594



Confidentiality Warning: This message and any attachments are intended only for the use of the intended recipient(s), are confidential, and may be privileged. If you are not the intended recipient, you are hereby notified that any review, retransmission, conversion to hard copy, copying, circulation or other use of all or any portion of this message and any attachments is strictly prohibited. If you are not the intended recipient, please notify the sender immediately by return e-mail, and delete this message and any attachments from your system.