

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

# NM OIL CONSERVATION

ARTESTA DISTRICT

Form C-141

JUN 13 2017 Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

## Release Notification and Corrective Action

NAB1718135920		OPERATOR		<input checked="" type="checkbox"/> Initial Report	<input checked="" type="checkbox"/> Final Report
Name of Company	OGRID Number	Contact			
EOG Y Resources, Inc.	25575	Robert Asher			
Address	Telephone No.				
104 S. 4 <sup>th</sup> Street	575-748-1471				
Facility Name	Facility Type				
Sears BRS #2H	Battery				
Surface Owner	Mineral Owner	API No.			
Fee	Fee	30-015-41583			

## LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	21	18S	26E	300	North	220	West	Eddy

Latitude 32.73985 Longitude 104.39485

## NATURE OF RELEASE

Type of Release	Volume of Release	Volume Recovered
Produced Water	5 B/PW	5 BPW
Source of Release	Date and Hour of Occurrence	Date and Hour of Discovery
Steel production line	5/19/2017; AM	5/19/2017; AM
Was Immediate Notice Given?	If YES, To Whom?	
<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	NA	
By Whom?	Date and Hour	
NA	NA	
Was a Watercourse Reached?	If YES, Volume Impacting the Watercourse.	
<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		

If a Watercourse was Impacted, Describe Fully.\*



Describe Cause of Problem and Remedial Action Taken.\*

A steel production line within the battery developed a hole causing the release. Closed valves to isolate the leak, vacuum truck(s) and roustabout crews were called.

Describe Area Affected and Cleanup Action Taken.\*

An approximate area of 40' X 10' within the lined/bermed battery. All released produced water was recovered using a vacuum truck (100%). Roustabout crew repaired the line. Depth to Ground Water: 50-99' (approximately 75', per ChevronTexaco Trend Map), Wellhead Protection Area: No, Distance to Surface Water Body: >1000', SITE RANKING IS 10. Based on the battery being lined/bermed and all released produced water was recovered, EOG Y Resources requests closure.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOC marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOC acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Robert Asher	Approved by Environmental Specialist	
Title: Environmental Supervisor	Approval Date: 6/29/17	Expiration Date: N/A
E-mail Address: Robert_Asher@eogresources.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: June 13, 2017	Phone: 575-748-4217	2RD. 4271

\* Attach Additional Sheets If Necessary

Please refer to the New Mexico Oil Conservation Division Website for updated form(s) at:

<http://www.emnrd.state.nm.us/OCD/forms.html>

Thank you

## **Weaver, Crystal, EMNRD**

---

**From:** Bob Asher <Bob\_Asher@eogresources.com>  
**Sent:** Tuesday, June 13, 2017 7:49 AM  
**To:** Bratcher, Mike, EMNRD; Weaver, Crystal, EMNRD  
**Subject:** Form C-141, Initial/Final Report (Sears BRS #2H)  
**Attachments:** Form C-141, Initial Final Report (Sears BSR #2H).pdf

Mike/Crystal,

I had completed the C-141 right after the release occurred, but it never made it from a Word document to being emailed to your office.

Contact me if there are any questions.

Thank you,

**Robert C. "Bob" Asher**  
**Environmental Supervisor**  
Safety & Environmental Department  
EOG Resources, Inc.  
Artesia Division  
Artesia, NM 88210  
575-748-4217 (Office)  
575-365-4021 (Cell)  
**EOG Safety Begins With YOUR Safety**

