



# AE Order Number Banner

## Report Description

This report shows an AE Order Number in Barcode format for purposes of scanning. The Barcode format is Code 39.



**App Number:** pENV00003RP312

**3RP - 312**

**WILLIAMS FOUR CORNERS, LLC**

6/12/2017

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

OIL CONS. DIV DIST. 3 Form C-141  
Revised August 8, 2011  
MAY 18 2017  
Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

### Release Notification and Corrective Action

#### OPERATOR

☒ Initial Report ☒ Final Report

Name of Company: Williams Four Corners LLC	Contact: Mitch Morris	
Address: 1755 Arroyo Drive, Bloomfield, NM 87413	Telephone No.: (505) 632-4708	
Facility Name: Dogie Compressor Station	Facility Type: Compressor Station	
Surface Owner: Bureau of Land Management	Mineral Owner	API No.

#### LOCATION OF RELEASE

Unit Letter D	Section 4	Township 25N	Range 6W	Feet from the	North/South Line	Feet from the	East/West Line	County Rio Arriba
------------------	--------------	-----------------	-------------	---------------	------------------	---------------	----------------	----------------------

Latitude 36.43348° N Longitude -107.48061° W

#### NATURE OF RELEASE

Type of Release: Natural Gas	Volume of Release: 85 MCF Natural Gas	Volume Recovered: 0 MCF Natural gas
Source of Release: PSV	Date and Hour of Occurrence: Estimated 5/06/17 at 02:05 PM MST	Date and Hour of Discovery: Estimated 5/06/17 at 02:05 PM MST
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? N/A	
By Whom? N/A	Date and Hour: N/A	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*  Not Applicable		
Describe Cause of Problem and Remedial Action Taken.*  A fuel gas regulator failure caused an overpressure condition, allowing a PSV (pressure safety device) to open. The fuel gas regulator was repaired and placed back into service.		
Describe Area Affected and Cleanup Action Taken.*  No cleanup required on natural gas releases vented to atmosphere.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

#### OIL CONSERVATION DIVISION

Signature: 	Approved by Environmental Specialist: 	
Printed Name: Mitch Morris		
Title: Environmental Specialist	Approval Date: <u>6/12/2017</u>	Expiration Date:
E-mail Address: mitch.morris@williams.com	Conditions of Approval: 	Attached <input type="checkbox"/>
Date: 5/15/17 Phone: (505) 632-4708		

\* Attach Additional Sheets If Necessary

NF1716333170