District I 1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Form C-141 Revised October 10, 2003

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action										
				<b>OPERAT</b>	OR		🔲 Initi	al Report		Final Report
Name of C	ompany	y: Chesape	ake En	ergy		Contact: Bradley Blevins				
Address: P.O. Box 190						<b>Telephone No.:</b> (505) 391-1462 ext. 6224				
Facility Na			ge Unit	#5		Facility Type: Tank Battery				
Surface O	wner: Ji	m Keller		Mineral (						
						OF RELEAS				
Unit Letter	Section	Township	Range	Feet from the		rth/South Line	Feet from the	East/West Li	ne	County
L	33	23S	34E	2,310		S	990	W		Lea
		Lat	itude: <u>1</u>	N 32° 15' 36.66	<u>5"</u> L	ongitude: <u>W</u>	′ 103° 28' 49.	<u> 19"</u>		
				NATURI	E <b>O</b> I	F RELEASE				
Type of Release: Petroleum and/or production fluids						Volume of Re	lease: Unknown	Volume Re	ecovered	l: Unknown
Source of Release: Various sources							te and Hour of Occurrence: Date and Hour of Discovery:			
Was Immediate Notice Given? ☐ Yes ☐ No ☒ Not Require					ired	If YES, To Whom?				
By Whom? Bradley Blevins					Date and Hou	m:	· · · <u>·</u> ·			
Was a Watercourse Reached?						ne Impacting the	Watercourse:			
☐ Yes ⊠ No						Not Applicable				
If a Watercourse was Impacted, Describe Fully.* Not Applicable										
	Describe Cause of Problem and Remedial Action Taken.* The release is historical from various sources.  Describe Area Affected and Cleanup Action Taken.* Approximately 1,700 square-feet of surface area was impacted by the release. Soil borings									
				e extent of impacted is true and complete						
				t and/or file certain						
endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground wat										
surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility										
for compliance with any other federal, state, or local laws and/or regulation					OIL CONSERVATION DIVISION					
					. 1					
Signature: Sindly Slave										
Printed Name: Bradley Blevins  Approved by District Supervisor:										
Title: Field Supervisor					Approval Date:	Expiration Date:				
E-mail Address: bblevins@chkenergy.com					Conditions of Approval:		ned □			
Date: 9-3-56 Phone: (505) 391-1462 ext. 6224										
* Attach Ad										
Checapeake 147179  Jacility - FRACO609631183  application - placo609631474  Incident - n PACO609631284  Incident - n PACO609631284  Antelope Ridge Unit # 16004										
facilit	ty - f	4ACO609	63115	<b>)</b>	Ω	marco tona	-pPACOC	19/2/1/1	1	
<del>- ()</del>	$\theta$	a SAV Ma	19621	284	1	O O	PINOU	141	Ante	lope Ridge Unit #.
Mident - n PACOO763 (284)										



30 March 2006

Mr. Larry Johnson, Environmental Engineer New Mexico Oil Conservation Division 1625 North French Drive Hobbs, New Mexico 88240



Re: Initial C-141

Chesapeake Energy Antelope Ridge Unit #5 – Reference #160046 UL-L, Section 33, Township 23 South, Range 34 East Latitude N 32° 15' 36.66" and Longitude W 103° 28' 49.19"

Dear Mr. Johnson:

Environmental Plus, Inc. (EPI), on behalf of Mr. Bradley Blevins, Chesapeake Energy Corporation (Chesapeake), submits the attached New Mexico Oil Conservation Division (NMOCD) form C-141 for the above-referenced leak site, located on land owned by Jim Keller.

The site is located approximately 20 miles northwest of Jal, New Mexico (reference *Figure 1*). Information obtained from the New Mexico Office of the State Engineer's website and a United States Geological Survey (USGS) database indicates there are no water supply wells within a 1,000-foot radius of the release site. However, there are three water supply wells located within a 1.0-mile radius of the release site (reference *Figure 2*). Groundwater level data indicates an average depth to water of approximately 475 feet below ground surface (reference *Table 1*). The attached site information and metrics form ranks the site in accordance with the NMOCD Guidelines for Remediation of Leaks, Spills and Releases (August 13, 1993).

The historical release is of an unknown volume of petroleum and/or production fluids from varying sources.



Should you have any questions or concerns please feel free to contact me at (505) 394-3481 or via e-mail at <a href="mailto:iolness@envplus.net">iolness@envplus.net</a> or Mr. Bradley Blevins at (505) 391-1462 ext. 6224 or via e-mail at <a href="mailto:bblevins@chkenergy.com">bblevins@chkenergy.com</a>. All official communication should be addressed to:

Mr. Bradley Blevins Chesapeake Energy P.O. Box 190 Hobbs, New Mexico 88240

Sincerely,

ENVIRONMENTAL PLUS, INC.

Iain Olness, P.G. Hydrogeologist

cc: Bradley Blevins, Chesapeake Energy - Hobbs, NM


Curtis Blake, Chesapeake Energy – Hobbs, NM

Harlan Brown, Chesapeake Energy – Oklahoma City, OK


Jim Keller, Landowner

File












TABLE 1

Well Data


Chesapeake Energy - Antelope Ridge Unit #5 (Ref. # 160046)

	Well Number	Diversion <sup>A</sup>	Owner	Use	Twsp	Rng	Use Twsp Rng Sec q q q	Latitude	Longitude	Date Measured	Date Surface Measured Elevation <sup>B</sup>	Depth to Water
		_										(R bgs)
6	C 02386	3	RUBERT MADERA	DOM	24S	34E 0	4 214	DOM 24S 34E 04 214 N32° 15' 0.43"	W103° 28' 28.06" 31-Jan-60	31-Jan-60	3,555	475
	C 02397	30	BERT MADERA	COM	24S	34E 0	4 2 1 4	COM 24S 34E 04 2 1 4 N32° 15' 0.43"	W103° 28' 28.06"	31-Jan-60	3,555	475
	C 02397	E	BERT MADERA	MUL	24S	34E 0	4 2 1 4	MUL   248   34E   04 2 1 4   N32° 15'0.43"	W103° 28' 28.06"	31-Jan-60	3,555	475


<sup>8</sup> = Elevation interpolated from USGS topographical map based on referenced location.

COM = Commercial MUL = 72-12-1 Multiple domestic households

DOM = 72-12-1 Domestic quarters are 1=NW, 2=NE, 3=SW, 4=SE; quarters are biggest to smallest Shaded area indicates wells not shown in Figure 2




Photograph #1 - Lease sign.



Photograph #2 - Looking southwesterly at the release area and tank battery with berm.



Photograph #3-Looking west at release area.



Photograph #4-Looking north at release area.



**Incident Date:** Historical

NMOCD Notified:

**Assigned Site Reference:** #160046

Information and Metrics

Site: Antelope Ridge Unit #5 Company: Chesapeake Energy Street Address: 1616 West Bender Mailing Address: P.O. Box 190

City, State, Zip: Hobbs, New Mexico 88240

Representative: Bradley Blevins

**Representative Telephone:** (505) 391-1462 ext. 6224

Telephone:

Fluid volume released (bbls): Unknown Recovered (bbls): Unknown

>25 bbls: Notify NMOCD verbally within 24 hrs and submit form C-141 within 15 days.

(Also applies to unauthorized releases >500 mcf Natural Gas)

5-25 bbls: Submit form C-141 within 15 days (Also applies to unauthorized releases of 50-500 mcf Natural Gas)

Leak, Spill, or Pit (LSP) Name: Antelope Ridge Unit #5

Source of contamination:

Land Owner, i.e., BLM, ST, Fee, Other: Jim Keller

LSP Dimensions: 100 feet by 17 feet

LSP Area: ~1.700 ft<sup>2</sup>

**Location of Reference Point (RP):** 

Location distance and direction from RP:

Latitude: N 32° 15' 36.66" **Longitude:** W 103° 28' 49.19"

Elevation above mean sea level: 3,524 feet

**Feet from North Section Line:** Feet from West Section Line:

Location- Unit or 1/41/4: NW1/4 of the SW1/4

Unit Letter: L

**Location- Section: 33 Location- Township: T23S** 

Location- Range: R34E

Surface water body within 1000 'radius of site: none Domestic water wells within 1000' radius of site: none Agricultural water wells within 1000' radius of site: none

Public water supply wells within 1000' radius of site: none Depth from land surface to groundwater (DG): ~475 feet

Depth of contamination (DC): unknown

Depth to groundwater (DG – DC = DtGW):  $\sim$ 475 feet

1. Groundwater	2. Wellhead Protection Area	3. Distance to Surface Water Body
If Depth to GW <50 feet: 20 points	If <1000' from water source, or;<200' from	<200 horizontal feet: 20 points
If Depth to GW 50 to 99 feet: 10 points	private domestic water source: 20 points	200-1000 horizontal feet: 10 points
If Depth to GW >100 feet: 0 points	If >1000' from water source, or; >200' from private domestic water source: 0 points	>1000 horizontal feet: 0 points

Site Rank (1+2+3) = 0

Total Site Ranking Score and Acceptable Concentrations						
Parameter	>19	10-19	0-9			
Benzene <sup>1</sup>	10 ppm	10 ppm	10 ppm			
BTEX <sup>1</sup>	50 ppm	50 ppm	50 ppm			
TPH	100 ppm	1,000 ppm	5,000 ppm			
100 ppm field VC	OC headspace measurement ma	y be substituted for lab analysis				