

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised March 17, 1999

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

| | | | |
|-----------------|-------------------------------|---------------|---------------------|
| Name of Company | XTO Energy | Contact | Guy Pearce |
| Address | P.O. Box 700 Esbice NM 88231 | Telephone No. | (505) 441-1637 |
| Facility Name | North Vacuum ABO #203 Battery | Facility Type | Oil & Water Storage |
| Surface Owner | State of New Mexico | Mineral Owner | |
| | | Lease No. | |

LOCATION OF RELEASE

| | | | | | | | | |
|-------------|---------|----------|-------|---------------|------------------|---------------|----------------|--------|
| Unit Letter | Section | Township | Range | Feet from the | North/South Line | Feet from the | East/West Line | County |
| H | 22 | 17s | 34E | | | | | |

121'

NATURE OF RELEASE

| | | | | | |
|-----------------------------|---|---|-----------------------------------|----------------------------|------------------|
| Type of Release | Crude oil | Volume of Release | 50 bbls | Volume Recovered | 10 bbls |
| Source of Release | | Date and Hour of Occurrence | 4/8/06 | Date and Hour of Discovery | 4/8/06 9:00 a.m. |
| Was Immediate Notice Given? | <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required | If YES, To Whom? | Left message on the on-call phone | | |
| By Whom? | Cliff Green | Date and Hour | 4/8/06 | 1:00 pm | |
| Was a Watercourse Reached? | <input type="checkbox"/> Yes <input type="checkbox"/> No | If YES, Volume Impacting the Watercourse. | | | |

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

1/2" Ball valve on Head switch at the bottom of tank was left open. 50 bbls of oil spilled to ground. 10 bbls was recovered. Contaminated soil was scooped up with a backhoe and put on plastic.

Describe Area Affected and Cleanup Action Taken.*

Area 6' x 90' just east and south of tanks was affected. After spill was picked up and put on plastic the site is being sampled for further remediation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

| | | | |
|----------------------------------|------------------------|---|-----------------------------------|
| Signature: <u>Guy Pearce</u> | | OIL CONSERVATION DIVISION | |
| Printed Name: <u>Guy Pearce</u> | | Approved by <input type="checkbox"/> District Supervisor: | |
| Title: <u>Production Foreman</u> | | Approval Date: | Expiration Date: |
| Date: <u>4/10/06</u> | Phone: <u>441-1637</u> | Conditions of Approval: | Attached <input type="checkbox"/> |

Attach Additional Sheets If Necessary

XTO-5380
facility - APAC 0610051583
incident - NPAC 0610051645
application - PPAC 06100