




AE Order Number Banner

Report Description

This report shows an AE Order Number in Barcode format for purposes of scanning. The Barcode format is Code 39.



App Number: pCS1716332215

3RP - 1049

WPX ENERGY PRODUCTION, LLC

8/31/2017

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

OIL CONS. DIV DIST. 3

AUG 09 2017

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company WPX Energy Production, LLC	Contact Deborah Watson
Address PO Box 640	Telephone No. 505-333-1880
Facility Name WLU Remote #2	Facility Type

Surface Owner Federal	Mineral Owner Federal (NMNM-025830)	API No.
-----------------------	-------------------------------------	---------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	18	23N	08W	231	North	820	West	San Juan

Latitude N36.23358 Longitude W107.72862

NATURE OF RELEASE

Type of Release produced water	Volume of Release 10 bbl	Volume Recovered 10 bbl
Source of Release hammer union on water line	Date and Hour of Occurrence 5/14/17 14:00	Date and Hour of Discovery 5/14/17 14:00
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom? N/A	Date and Hour 5/15/17 13:05 followed by email.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*
N/A



Describe Cause of Problem and Remedial Action Taken.*

Hammer union in water can came loose releasing produced water into water can. Water truck called to the facility and recovered 10 bbl of produced water from within the water can.

Describe Area Affected and Cleanup Action Taken.*

- A water truck recovered 10 bbl of released fluids.
- Cleanup consisted of recovery of released fluids, washing of equipment (5/25), and removal and disposal of impacted soil (5/25).
- On May 30, 2017, one five-point composite sample was collected from within the water can (impacted area). Vanessa Fields, NMOCD, was present during the sampling event. The sample was laboratory analyzed for BTEX, TPH (GRO/DRO/MRO), and chlorides.
- Laboratory analytical results for BTEX and TPH were reported below the applicable NMOCD RRAL. (Laboratory results are attached)
- WPX applied gypsum to the impacted area within the water can on July 26. (see attached approval/communication with NMOCD)
- No further action required.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Deborah Watson	Approved by Environmental Specialist: 	
Title: Environmental Specialist	Approval Date: 8/31/2017	Expiration Date:
E-mail Address: deborah.watson@wpxenergy.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 08/8/2017	Phone: 505-333-1880	

* Attach Additional Sheets If Necessary

NCS1716331462



Hall Environmental Analysis Laboratory
4901 Hawkins NE
Albuquerque, NM 87109
TEL: 505-345-3975 FAX: 505-345-4107
Website: www.hallenvironmental.com

June 08, 2017

Debbie Watson

WPX Energy

721 S Main Ave

Aztec, NM 87410

TEL: (505) 333-1880

FAX

RE: WLU Remote #2 Water Can

OrderNo.: 1706020

Dear Debbie Watson:

Hall Environmental Analysis Laboratory received 1 sample(s) on 6/1/2017 for the analyses presented in the following report.

These were analyzed according to EPA procedures or equivalent. To access our accredited tests please go to www.hallenvironmental.com or the state specific web sites. In order to properly interpret your results, it is imperative that you review this report in its entirety. See the sample checklist and/or the Chain of Custody for information regarding the sample receipt temperature and preservation. Data qualifiers or a narrative will be provided if the sample analysis or analytical quality control parameters require a flag. When necessary, data qualifiers are provided on both the sample analysis report and the QC summary report, both sections should be reviewed. All samples are reported, as received, unless otherwise indicated. Lab measurement of analytes considered field parameters that require analysis within 15 minutes of sampling such as pH and residual chlorine are qualified as being analyzed outside of the recommended holding time.

Please don't hesitate to contact HEAL for any additional information or clarifications.

ADHS Cert #AZ0682 -- NMED-DWB Cert #NM9425 -- NMED-Micro Cert #NM0190

Sincerely,

Andy Freeman

Laboratory Manager

4901 Hawkins NE

Albuquerque, NM 87109

Hall Environmental Analysis Laboratory, Inc.

Analytical Report

Lab Order 1706020

Date Reported: 6/8/2017

CLIENT: WPX Energy

Client Sample ID: SC-1

Project: WLU Remote #2 Water Can

Collection Date: 5/30/2017 1:33:00 PM

Lab ID: 1706020-001

Matrix: SOIL

Received Date: 6/1/2017 7:20:00 AM

Analyses	Result	PQL	Qual	Units	DF	Date Analyzed	Batch
EPA METHOD 300.0: ANIONS							Analyst: MRA
Chloride	5000	300		mg/Kg	200	6/5/2017 5:18:10 PM	32082
EPA METHOD 8015M/D: DIESEL RANGE ORGANICS							Analyst: TOM
Diesel Range Organics (DRO)	ND	9.6		mg/Kg	1	6/2/2017 12:51:51 PM	32064
Motor Oil Range Organics (MRO)	ND	48		mg/Kg	1	6/2/2017 12:51:51 PM	32064
Surr: DNOP	101	70-130		%Rec	1	6/2/2017 12:51:51 PM	32064
EPA METHOD 8015D: GASOLINE RANGE							Analyst: NSB
Gasoline Range Organics (GRO)	ND	5.0		mg/Kg	1	6/2/2017 5:32:46 PM	32063
Surr: BFB	100	54-150		%Rec	1	6/2/2017 5:32:46 PM	32063
EPA METHOD 8021B: VOLATILES							Analyst: NSB
Benzene	ND	0.025		mg/Kg	1	6/2/2017 5:32:46 PM	32063
Toluene	ND	0.050		mg/Kg	1	6/2/2017 5:32:46 PM	32063
Ethylbenzene	ND	0.050		mg/Kg	1	6/2/2017 5:32:46 PM	32063
Xylenes, Total	ND	0.099		mg/Kg	1	6/2/2017 5:32:46 PM	32063
Surr: 4-Bromofluorobenzene	121	66.6-132		%Rec	1	6/2/2017 5:32:46 PM	32063

Refer to the QC Summary report and sample login checklist for flagged QC data and preservation information.

Qualifiers:	*	Value exceeds Maximum Contaminant Level.	B	Analyte detected in the associated Method Blank
	D	Sample Diluted Due to Matrix	E	Value above quantitation range
	H	Holding times for preparation or analysis exceeded	J	Analyte detected below quantitation limits
	ND	Not Detected at the Reporting Limit	P	Sample pH Not In Range
	R	RPD outside accepted recovery limits	RL	Reporting Detection Limit
	S	% Recovery outside of range due to dilution or matrix	W	Sample container temperature is out of limit as specified

QC SUMMARY REPORT

Hall Environmental Analysis Laboratory, Inc.

WO#: 1706020

08-Jun-17

Client: WPX Energy

Project: WLU Remote #2 Water Can

Sample ID	MB-32082		SampType:	MBLK		TestCode:	EPA Method 300.0: Anions			
Client ID:	PBS		Batch ID:	32082		RunNo:	43225			
Prep Date:	6/2/2017		Analysis Date:	6/2/2017		SeqNo:	1361223		Units: mg/Kg	
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	%RPD	RPDLimit	Qual
Chloride	ND	1.5								

Sample ID	LCS-32082		SampType:	LCS		TestCode:	EPA Method 300.0: Anions			
Client ID:	LCSS		Batch ID:	32082		RunNo:	43225			
Prep Date:	6/2/2017		Analysis Date:	6/2/2017		SeqNo:	1361224		Units: mg/Kg	
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	%RPD	RPDLimit	Qual
Chloride	14	1.5	15.00	0	93.8	90	110			

Qualifiers:

* Value exceeds Maximum Contaminant Level.
D Sample Diluted Due to Matrix
H Holding times for preparation or analysis exceeded
ND Not Detected at the Reporting Limit
R RPD outside accepted recovery limits
S % Recovery outside of range due to dilution or matrix

B Analyte detected in the associated Method Blank
E Value above quantitation range
J Analyte detected below quantitation limits
P Sample pH Not In Range
RL Reporting Detection Limit
W Sample container temperature is out of limit as specified

QC SUMMARY REPORT

Hall Environmental Analysis Laboratory, Inc.

WO#: 1706020

08-Jun-17

Client: WPX Energy
Project: WLU Remote #2 Water Can

Sample ID	LCS-32064		SampType:	LCS		TestCode:	EPA Method 8015M/D: Diesel Range Organics			
Client ID:	LCSS		Batch ID:	32064		RunNo:	43209			
Prep Date:	6/1/2017		Analysis Date:	6/2/2017		SeqNo:	1360326		Units: mg/Kg	
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	%RPD	RPDLimit	Qual
Diesel Range Organics (DRO)	44	10	50.00	0	87.3	73.2	114			
Surr: DNOP	4.7		5.000		94.5	70	130			

Sample ID	MB-32064		SampType:	MBLK		TestCode:	EPA Method 8015M/D: Diesel Range Organics			
Client ID:	PBS		Batch ID:	32064		RunNo:	43209			
Prep Date:	6/1/2017		Analysis Date:	6/2/2017		SeqNo:	1360330		Units: mg/Kg	
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	%RPD	RPDLimit	Qual
Diesel Range Organics (DRO)	ND	10								
Motor Oil Range Organics (MRO)	ND	50								
Surr: DNOP	9.5		10.00		95.1	70	130			

Qualifiers:

- | | |
|---|---|
| * Value exceeds Maximum Contaminant Level. | B Analyte detected in the associated Method Blank |
| D Sample Diluted Due to Matrix | E Value above quantitation range |
| H Holding times for preparation or analysis exceeded | J Analyte detected below quantitation limits |
| ND Not Detected at the Reporting Limit | P Sample pH Not In Range |
| R RPD outside accepted recovery limits | RL Reporting Detection Limit |
| S % Recovery outside of range due to dilution or matrix | W Sample container temperature is out of limit as specified |

QC SUMMARY REPORT

Hall Environmental Analysis Laboratory, Inc.

WO#: 1706020

08-Jun-17

Client: WPX Energy

Project: WLU Remote #2 Water Can

Sample ID	MB-32063		SampType: MBLK		TestCode: EPA Method 8015D: Gasoline Range					
Client ID:	PBS		Batch ID: 32063		RunNo: 43219					
Prep Date:	6/1/2017		Analysis Date: 6/2/2017		SeqNo: 1360983		Units: mg/Kg			
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	%RPD	RPDLimit	Qual
Gasoline Range Organics (GRO)	ND	5.0								
Surr: BFB	1000		1000		100	54	150			

Sample ID	LCS-32063		SampType: LCS		TestCode: EPA Method 8015D: Gasoline Range					
Client ID:	LCSS		Batch ID: 32063		RunNo: 43219					
Prep Date:	6/1/2017		Analysis Date: 6/2/2017		SeqNo: 1360984		Units: mg/Kg			
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	%RPD	RPDLimit	Qual
Gasoline Range Organics (GRO)	26	5.0	25.00	0	103	76.4	125			
Surr: BFB	1000		1000		103	54	150			

Qualifiers:

- | | |
|---|---|
| * Value exceeds Maximum Contaminant Level. | B Analyte detected in the associated Method Blank |
| D Sample Diluted Due to Matrix | E Value above quantitation range |
| H Holding times for preparation or analysis exceeded | J Analyte detected below quantitation limits |
| ND Not Detected at the Reporting Limit | P Sample pH Not In Range |
| R RPD outside accepted recovery limits | RL Reporting Detection Limit |
| S % Recovery outside of range due to dilution or matrix | W Sample container temperature is out of limit as specified |

QC SUMMARY REPORT

Hall Environmental Analysis Laboratory, Inc.

WO#: 1706020

08-Jun-17

Client: WPX Energy

Project: WLU Remote #2 Water Can

Sample ID	MB-32063		SampType:	MBLK		TestCode:	EPA Method 8021B: Volatiles			
Client ID:	PBS		Batch ID:	32063		RunNo:	43219			
Prep Date:	6/1/2017		Analysis Date:	6/2/2017		SeqNo:	1361003	Units:	mg/Kg	
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	%RPD	RPDLimit	Qual
Benzene	ND	0.025								
Toluene	ND	0.050								
Ethylbenzene	ND	0.050								
Xylenes, Total	ND	0.10								
Surr: 4-Bromofluorobenzene	1.2		1.000		124	66.6	132			

Sample ID	LCS-32063		SampType:	LCS		TestCode:	EPA Method 8021B: Volatiles			
Client ID:	LCSS		Batch ID:	32063		RunNo:	43219			
Prep Date:	6/1/2017		Analysis Date:	6/2/2017		SeqNo:	1361004	Units:	mg/Kg	
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	%RPD	RPDLimit	Qual
Benzene	1.0	0.025	1.000	0	102	80	120			
Toluene	1.0	0.050	1.000	0	102	80	120			
Ethylbenzene	1.0	0.050	1.000	0	102	80	120			
Xylenes, Total	3.1	0.10	3.000	0	104	80	120			
Surr: 4-Bromofluorobenzene	1.2		1.000		119	66.6	132			

Qualifiers:

* Value exceeds Maximum Contaminant Level.	B Analyte detected in the associated Method Blank
D Sample Diluted Due to Matrix	E Value above quantitation range
H Holding times for preparation or analysis exceeded	J Analyte detected below quantitation limits
ND Not Detected at the Reporting Limit	P Sample pH Not In Range
R RPD outside accepted recovery limits	RL Reporting Detection Limit
S % Recovery outside of range due to dilution or matrix	W Sample container temperature is out of limit as specified



Hall Environmental Analysis Laboratory
4901 Hawkins NE
Albuquerque, NM 87109
TEL: 505-345-3975 FAX: 505-345-4107
Website: www.hallenvironmental.com

Sample Log-In Check List

Client Name: WPX ENERGY

Work Order Number: 1706020

RcptNo: 1

Received By: Anne Thorne

6/1/2017 7:20:00 AM

Anne Thorne

Completed By: Anne Thorne

6/1/2017 10:01:36 AM

Anne Thorne

Reviewed By: *SRL* 06/01/17

Chain of Custody

1. Custody seals intact on sample bottles? Yes ☐ No ☐ Not Present ☒
2. Is Chain of Custody complete? Yes ☒ No ☐ Not Present ☐
3. How was the sample delivered? Courier

Log In

4. Was an attempt made to cool the samples? Yes ☒ No ☐ NA ☐
5. Were all samples received at a temperature of $>0^{\circ}\text{C}$ to 6.0°C ? Yes ☒ No ☐ NA ☐
6. Sample(s) in proper container(s)? Yes ☒ No ☐
7. Sufficient sample volume for indicated test(s)? Yes ☒ No ☐
8. Are samples (except VOA and ONG) properly preserved? Yes ☒ No ☐
9. Was preservative added to bottles? Yes ☐ No ☒ NA ☐
10. VOA vials have zero headspace? Yes ☐ No ☐ No VOA Vials ☒
11. Were any sample containers received broken? Yes ☐ No ☒
12. Does paperwork match bottle labels?
(Note discrepancies on chain of custody) Yes ☒ No ☐
13. Are matrices correctly identified on Chain of Custody? Yes ☒ No ☐
14. Is it clear what analyses were requested? Yes ☒ No ☐
15. Were all holding times able to be met?
(If no, notify customer for authorization.) Yes ☒ No ☐
of preserved bottles checked for pH: _____
(<2 or >12 unless noted)
Adjusted? _____
Checked by: _____

Special Handling (if applicable)

16. Was client notified of all discrepancies with this order? Yes ☐ No ☐ NA ☒

Person Notified:

Date

By Whom:

Via: ☐ eMail ☐ Phone ☐ Fax ☐ In Person

Regarding:

Client Instructions:

17. Additional remarks:

18. Cooler Information

Cooler No	Temp $^{\circ}\text{C}$	Condition	Seal Intact	Seal No	Seal Date	Signed By
1	1.7	Good	Yes			

Watson, Debbie

From: Smith, Cory, EMNRD <Cory.Smith@state.nm.us>
Sent: Monday, June 19, 2017 7:06 AM
To: Watson, Debbie; Fields, Vanessa, EMNRD; Thomas, Leigh
Subject: [EXTERNAL] RE: WLU Remote #2 Water Can Lab Results

CAUTION: This email was sent from an EXTERNAL source. Use caution when clicking links or opening attachments.

Debbie,

OCD approved your plan, please include this on your final C-141.

Thanks

Cory Smith
Environmental Specialist
Oil Conservation Division
Energy, Minerals, & Natural Resources
1000 Rio Brazos, Aztec, NM 87410
(505)334-6178 ext 115
cory.smith@state.nm.us

From: Watson, Debbie [mailto:Deborah.Watson@wpenergy.com]
Sent: Monday, June 19, 2017 6:39 AM
To: Smith, Cory, EMNRD <Cory.Smith@state.nm.us>; Fields, Vanessa, EMNRD <Vanessa.Fields@state.nm.us>; Thomas, Leigh <l1thomas@blm.gov>
Subject: WLU Remote #2 Water Can Lab Results

Attached is the laboratory report for the confirmation sample collected from the WLU Remote #2 water can. The laboratory results were below applicable NMOCD RRAL for BTEX and TPH. The chloride concentration was reported at 5,000 mg/kg. WPX requests closure/backfilling of the excavated area following application of gypsum to the impacted area within the water can. Please note the impacted area is contained, is located greater than 8 feet below ground surface, and depth to ground water exceeds 100 feet. Please contact me with any questions.

Thank you,

Debbie

Deborah Watson
Environmental Specialist
PO Box 640 | Aztec, NM 87410
office 505.333.1880 | cell 505.386.9693 | fax 505.333.1805
deborah.watson@wpenergy.com

