

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141
Revised August 8, 2011

SEP 13 2017

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1725731840 **OPERATOR** ☒ Initial Report ☒ Final Report

Name of Company Devon Energy Production Company 1037	Contact Wesley Ryan-Production Foreman
Address 6488 Seven Rivers Hwy Artesia, NM 88210	Telephone No. 575-390-5436
Facility Name Coral PWU 28 #4H	Facility Type Oil

Surface Owner State	Mineral Owner State	API No 30-015-39328
----------------------------	----------------------------	----------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
p	28	19S	29E	330	FSL	990	FEL	EDDY

Latitude: 32.625351

Longitude: -104.0745087

NATURE OF RELEASE

Type of Release Oil	Volume of Release 12 bbls	Volume Recovered 12 bbls
Source of Release Oil storage tank	Date and Hour of Occurrence 9/1/2017 12:04 PM	Date and Hour of Discovery 9/1/2017 12:04 PM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? N/A	
By Whom? N/A	Date and Hour N/A	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse N/A	

If a Watercourse was Impacted, Describe Fully.*N/A

Describe Cause of Problem and Remedial Action Taken.*

The hammer unions on the discharge line of the circulation pump became loose causing Oil to spill out of the storage tank. Upon discovery the valves were isolated and shut off and the union valves were immediately tighten and repaired.

Describe Area Affected and Cleanup Action Taken.*

12 BBLS of Oil was released from the storage tank. A vacuum truck was dispatched and 12 BBLS of Oil was recovered. The release originated from the Oil storage tank and was released into the lined SPCC containment. The approximate affected area is 10' x 50' on the well pad inside the lined containment. Once fluids were removed the liner was visually inspected by Devon field staff for any pinholes or punctures and none were found. Based on this inspection there is no evidence that the spill fluids left containment.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Jennifer Reyna</i>	OIL CONSERVATION DIVISION	
Printed Name: Jennifer Reyna	Signed By <i>[Signature]</i> Approved by Environmental Specialist:	
Title: Field Admin Support	Approval Date: 9/14/17	Expiration Date: N/A
E-mail Address: jennifer.reyna@dvn.com	Conditions of Approval: FINAL	
Date: 9/13/2017 Phone: 575.746.5588	Attached <input checked="" type="checkbox"/> <i>ARP-4386</i>	

* Attach Additional Sheets If Necessary

Bratcher, Mike, EMNRD

From: Reyna, Jennifer <Jennifer.Reyna@dvn.com>
Sent: Wednesday, September 13, 2017 8:53 AM
To: Bratcher, Mike, EMNRD; Weaver, Crystal, EMNRD; Amber Groves (agroves@slo.state.nm.us)
Cc: Shoemaker, Mike; Fulks, Brett; Ryan, Wesley; Aguilar, Leonard
Subject: Coral PWU 28-4H_12bbls oil_9-1-17
Attachments: Coral PWU 28-4H_12bbls oil_9-1-17 intial C-141.doc; Coral PWU 28-4H_12bbls oil_9-1-17 GIS Image.pdf

Good Morning,

Attached please find the Initial C-141 and GIS Image for the 12 bbls of oil release at the Coral PWU 28-4H on 9.1.17.

If you have any questions please feel free to contact me.

Thank you,

Jennifer Reyna

Field Admin Support
Production
B-Schedule

Devon Energy Corporation
P.O. Box 250
Artesia, NM 88211
575 746 5588

Confidentiality Warning: This message and any attachments are intended only for the use of the intended recipient(s), are confidential, and may be privileged. If you are not the intended recipient, you are hereby notified that any review, retransmission, conversion to hard copy, copying, circulation or other use of all or any portion of this message and any attachments is strictly prohibited. If you are not the intended recipient, please notify the sender immediately by return e-mail, and delete this message and any attachments from your system.

Coral PWU 28-4H

12 BBLs Oil_9-1-17 GIS Image



WGS_1984_Web_Mercator_Auxiliary_Sphere
Prepared by: Jennifer Reyna
Map is current as of: 05-Sep-2017

This map is for illustrative purposes only and is neither a legally recorded map nor survey and is not intended to be used as one. Devon makes no warranty, representation or claim of any kind regarding this map.



- Address Search
- Elevation Points
- All Orders
- HIGH
- MEDIUM 3
- MEDIUM 2
- LOW
- INFREQUENT

S28-T19S-R29E

CORAL 28 PWU BATTERY

CORAL PWU 28-4H

