

# NM OIL CONSERVATION

# NM OIL CONSERVATION

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

ARTESIA DISTRICT

State of New Mexico

ARTESIA DISTRICT

DEC 21 2017 Energy Minerals and Natural Resources

Form C-141  
Revised April 3, 2017

Oil Conservation Division

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

1220 South St. Francis Dr. RECEIVED  
Santa Fe, NM 87505

## Release Notification and Corrective Action

NAB1736136697 OPERATOR ☒ Initial Report ☐ Final Report

Name of Company: XTO Energy 5380	Contact: Kyle Littrell
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No: 432-221-7331
Facility Name: Corral Canyon Federal Com #013H	Facility Type: Exploration and Production
Surface Owner: State of NM	Mineral Owner: State of NM
API No: 30-015-43493	

## LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	6	25S	29E	140	South	385	East	Eddy

Latitude 32.152439° Longitude -104.016389° NAD83

## NATURE OF RELEASE

Type of Release	Crude Oil	Volume of Release	24 bbls	Volume Recovered	24 bbls
Source of Release	Frac Tank	Date and Hour of Occurrence	12/13/2017 time unknown	Date and Hour of Discovery	12/13/2017 1 am
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	N/A		
By Whom?	N/A	Date and Hour:	N/A		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	N/A		
If a Watercourse was Impacted, Describe Fully.* N/A					
Describe Cause of Problem and Remedial Action Taken.* Fluid escaped from the frac tank side manway plate. The plate was tightened.					
Describe Area Affected and Cleanup Action Taken.* The leak affected the temporary impermeable lined containment surrounding the frac tanks. No fill material was located inside containment. A XTO EHS Coordinator who is competent in the operation, maintenance, and inspection of all on-site equipment and facilities visually inspected the containment and verified there was no visual evidence of a liner breach. All free-standing liquids were recovered from the containment. The frac job is anticipated to last another month. Once completed, the frac tanks will be removed and the containment will be power washed and removed from location.					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.					

## OIL CONSERVATION DIVISION

Signature:	Approved by Environmental Specialist:	
Printed Name: Kyle Littrell	Approval Date: 12/21/17	Expiration Date: N/A
Title: Environmental Coordinator	Conditions of Approval: see attached	
E-mail Address: Kyle.Littrell@xtoenergy.com	Attached:	
Date: 12/21/2017 Phone: 432-221-7331		

\* Attach Additional Sheets If Necessary

12/22/17 AB

Operator/Responsible Party,

The OCD has received the form C-141 you provided on **12/21/17** regarding an unauthorized release. The information contained on that form has been entered into our incident database and remediation case number ARP-4534 has been assigned. **Please refer to this case number in all future correspondence.**

It is the Division's obligation under both the Oil & Gas Act and Water Quality Act to provide for the protection of public health and the environment. Our regulations (19.15.29.11 NMAC) state the following,

*The responsible person shall complete division-approved corrective action for releases that endanger public health or the environment. The responsible person shall address releases in accordance with a remediation plan submitted to and approved by the division or with an abatement plan submitted in accordance with 19.15.30 NMAC. [emphasis added]*

Release characterization is the first phase of corrective action unless the release is ongoing or is of limited volume and all impacts can be immediately addressed. Proper and cost-effective remediation typically cannot occur without adequate characterization of the impacts of any release. Furthermore, the Division has the ability to impose reasonable conditions upon the efforts it oversees. **As such, the Division is requiring a workplan for the characterization of impacts associated with this release be submitted to the OCD District II office in Artesia on or before 1/21/18. If and when the release characterization workplan is approved, there will be an associated deadline for submittal of the resultant investigation report. Modest extensions of time to these deadlines may be granted, but only with acceptable justification.**

The goals of a characterization effort are: 1) determination of the lateral and vertical extents along with the magnitude of soil contamination. 2) determine if groundwater or surface waters have been impacted. 3) If groundwater or surface waters have been impacted, what are the extents and magnitude of that impact. 4) The characterization of any other adverse impacts that may have occurred (examples: impacts on vegetation, impacts on wildlife, air quality, loss of use of property, etc.). To meet these goals as quickly as possible, the following items must, at a minimum, be addressed in the release characterization workplan and subsequent reporting:

- Horizontal delineation of soil impacts in each of the four cardinal compass directions. Adsorbed soil contamination must be characterized for the following constituents using the associated laboratory methods: benzene, toluene, ethylbenzene, and total xylenes by either Method 8260 or 8021, total petroleum hydrocarbons by Method 8015 extended range (GRO+DRO+MRO; C<sub>6</sub> thru C<sub>36</sub>), and for chloride by Method 300. This is not an exclusive list of potential contaminants. Analyzed parameters should be modified based on the nature of the released substance(s). Soil sampling must be both within the impacted area and beyond.
- Vertical delineation of soil impacts. Adsorbed soil contamination must be characterized for the following constituents using the associated laboratory methods: benzene, toluene, ethylbenzene, and total xylenes by either Method 8260 or 8021, total petroleum hydrocarbons by Method 8015 extended range (GRO+DRO+MRO; C<sub>6</sub> thru C<sub>36</sub>), and for chloride by Method 300. As above, this is not an exclusive list of potential contaminants and can be modified. Vertical characterization samples should be taken at depth intervals no greater than five feet apart. Lithologic description of encountered soils must also be provided. At least ten vertical feet of soils with contaminant concentrations at or below these values must be demonstrated as existing above the water table.
- Nominal detection limits for field and laboratory analyses must be provided.
- Composite sampling is not generally allowed.
- Field screening and assessment techniques are acceptable (headspace, titration, EC [include algorithm for validation purposes], EM, etc.), but the sampling and assay procedures must be clearly defined. Copies of field notes are highly desirable. A statistically significant set of split samples must be submitted for confirmatory laboratory analysis, including the laterally farthest and vertically deepest sets of soil samples. Make sure there are at least two soil samples submitted

for laboratory analysis from each borehole or test pit (highest observed contamination and deepest depth investigated). Copies of the actual laboratory results must be provided including chain of custody documentation.

- Probable depth to shallowest protectable groundwater and lateral distance to nearest surface water. If there is an estimate of groundwater depth, the information used to arrive at that estimate must be provided. If there is a reasonable assumption that the depth to protectable water is 50 feet or less, the responsible party should anticipate the need for at least one groundwater monitoring well to be installed in the area of likely maximum contamination.

- If groundwater contamination is encountered, an additional investigation workplan may be required to determine the extents of that contamination. Groundwater and/or surface water samples, if any, must be analyzed by a competent laboratory for volatile organic hydrocarbons (typically Method 8260 full list), total dissolved solids, pH, major anions and cations including chloride and sulfate, dissolved iron, and dissolved manganese. The investigation workplan must provide the *groundwater sampling method(s) and sample handling protocols*. To the fullest extent possible, aqueous analyses must be undertaken using nominal method detection limits. As with the soil analyses, copies of the actual laboratory results must be provided including chain of custody documentation.

- Accurately scaled and well-drafted site maps must be provided providing the location of borings, test pits, monitoring wells, potentially impacted areas, and significant surface features including roads and site infrastructure that might limit either the release characterization or remedial efforts. Field sketches may be included in subsequent reporting, but should not be considered stand-alone documentation of the site's layout. Digital photographic documentation of the location and fieldwork is recommended, especially if unusual circumstances are encountered.

**Nothing herein should be interpreted to preclude emergency response actions or to imply immediate remediation by removal cannot proceed as warranted. Nonetheless, characterization of impacts and confirmation of the effectiveness of remedial efforts must still be provided to the OCD before any release incident will be closed.**

**Jim Griswold**

OCD Environmental Bureau Chief

1220 South St. Francis Drive

Santa Fe, New Mexico 87505

505-476-3465

jim.griswold@state.nm.us

## Weaver, Crystal, EMNRD

---

**From:** Weaver, Crystal, EMNRD  
**Sent:** Friday, December 22, 2017 12:44 PM  
**To:** 'Ruth, Amy'; Bratcher, Mike, EMNRD; Tucker, Shelly; Jim Amos  
**Cc:** Littrell, Kyle; Sanders, Toady; Foust, Bryan; McSpadden, Wes  
**Subject:** RE: Initial C-141 Corral Canyon 13 12-13-17

### Amy please note:

I am only sending this email reminding that the picture portion of the process mentioned below seems to be what remains to be done for this release, which is absolutely fine to be provided along with the Final C-141 form submission. All other requested tasks mentioned below appear to be already within the Initial C-141 form. Thank you.

*When an Initial/Final C-141 (in this case you only sent in an Initial C-141) is submitted for a release that is stated to be fully contained within secondary lined containment, OCD is asking that operators provide a written statement within the Initial/Final C-141 (**attesting to the integrity of the liner and stating that you yourself or another member of your organization ((that has been informed/educated on what to look for)) have inspected the liner, also if the containment involves any fill material OCD needs a statement on the form saying that all fill was removed and replaced**).*

*Aside from that request, OCD is also requesting for all operators to include two or 3 photos in the body of the email they send to us showing the condition of the battery before and after it was remediated/inspected. So what I mean by that is take the photos and drop them straight into the body of the email (just paste it right before where you have your signature block with your name and your title description). We want to ask all operators to include those since we have asked some of them to do so. So please if you could just drop us a few photos for this location, not as attachments but straight into the email, that would be awesome. One shot of the location sign and then like I said 2 or so more to represent how the battery/lined containment area looks pre and post.*

If you have any questions or concerns regarding this request please let us know.

### Crystal Weaver

Environmental Specialist  
OCD – Artesia District II  
811 S. 1<sup>st</sup> Street  
Artesia, NM 88210  
Office: 575-748-1283 ext. 101  
Cell: 575-840-5963  
Fax: 575-748-9720

**From:** Ruth, Amy [mailto:Amy\_Ruth@xtoenergy.com]  
**Sent:** Thursday, December 21, 2017 9:14 AM  
**To:** Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>; Weaver, Crystal, EMNRD <Crystal.Weaver@state.nm.us>;

## Weaver, Crystal, EMNRD

---

**From:** Ruth, Amy <Amy\_Ruth@xtoenergy.com>  
**Sent:** Thursday, December 21, 2017 9:14 AM  
**To:** Bratcher, Mike, EMNRD; Weaver, Crystal, EMNRD; Tucker, Shelly; Jim Amos  
**Cc:** Littrell, Kyle; Sanders, Toady; Foust, Bryan; McSpadden, Wes  
**Subject:** Initial C-141 Corral Canyon 13 12-13-17  
**Attachments:** Initial C-141 Corral Canyon 13 12-13-17.pdf

Good Morning,

Please find attached, an initial form C-141 detailing a release from the referenced facility. Thank you and feel free to call with any questions or concerns.

Respectfully,

*Amy C. Ruth*

Delaware Basin Division

Environmental Coordinator

3104 E. Greene Street | Carlsbad, NM 88220 | M: 432.661.0571 | O: 575.887.7329



This document may contain information that is privileged, confidential and exempt from disclosure under applicable law. If you are not the intended recipient, you are notified that any unauthorized disclosure, copying, distribution or action on/of the contents of this document is prohibited.