

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

NM OIL CONSERVATION
State of New Mexico ARTESIA DISTRICT
Energy Minerals and Natural Resources **JAN 10 2018**
Oil Conservation Division Submit 1 Copy to appropriate District Office in
1220 South St. Francis Dr. **RECEIVED** accordance with 19.15.29 NMAC.
Santa Fe, NM 87505

Form C-141
Revised April 3, 2017

Release Notification and Corrective Action

Initial only
 Initial Report Final Report

NAB1801757352

OPERATOR	
Name of Company <i>Devon Energy Production Company 40137</i>	Contact <i>Leonard Aguilar</i>
Address <i>6488 Seven Rivers Hwy Artesia, NM 88210</i>	Telephone No. <i>575-513-1930</i>
Facility Name <i>Strawberry 7 Fed Com 4H</i>	Facility Type <i>Oil</i>

Surface Owner <i>Federal</i>	Mineral Owner <i>Federal</i>	API No. <i>30-015-37258</i>
------------------------------	------------------------------	-----------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
<i>P</i>	<i>07</i>	<i>19S</i>	<i>31E</i>					<i>EDDY</i>

Latitude *32.66867* **Longitude** *103.90169* *NAD83*

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release <i>11 BBLs</i>	Volume Recovered <i>11 BBLs</i>
Source of Release Produced Water Flowline	Date and Hour of Occurrence <i>December 27, 2017 9:01 AM MST</i>	Date and Hour of Discovery <i>December 27, 2017 9:01 AM MST</i>
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <i>BLM-Shelly Tucker OCD-Mike Bratcher & Crystal Weaver</i>	
By Whom? <i>Leonard Aguilar-Assistant Foreman</i>	Date and Hour BLM & OCD <i>December 27, 2017 4:18 PM MST</i>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. <i>N/A</i>	
If a Watercourse was Impacted, Describe Fully.* <i>N/A</i>		
Describe Cause of Problem and Remedial Action Taken.* <i>The threaded 90 on a produced water flowline corroded causing the release. The flowline was isolated and wells were shut in to prevent any further release. The flowline was repaired.</i>		
Describe Area Affected and Cleanup Action Taken.* <i>Approximately 11 BBLs of produced water was released from the produced water flowline. All released fluids remained inside the lined SPCC containment ring. A vacuum truck was dispatched and approximately 11 BBLs of produced water was recovered. The approximate affected area is 25ft x 45ft. Once fluids were removed the liner was visually inspected by Devon field staff for any pinholes or punctures and none were found. Based on this inspection there is no evidence that the spill fluids left containment.</i>		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

Signature: <i>Jennifer Reyna</i> Printed Name: <i>Jennifer Reyna</i> Title: <i>Field Admin Support</i> E-mail Address: <i>Jennifer.Reyna@dvn.com</i> Date: <i>1/2/2018</i> Phone: <i>575.746.5588</i>	OIL CONSERVATION DIVISION Approved by Environmental Specialist: <i>Crystal W</i> Approval Date: <i>1/16/18</i> Expiration Date: <i>N/A</i> Conditions of Approval: <i>see attached</i> Attached <i>2 RP-45608</i>
---	--

* Attach Additional Sheets If Necessary

1/16/18 AB

Operator/Responsible Party,

The OCD has received the form C-141 you provided on **1/10/18** regarding an unauthorized release. The information contained on that form has been entered into our incident database and remediation case number ARP-45108 has been assigned. **Please refer to this case number in all future correspondence.**

It is the Division's obligation under both the Oil & Gas Act and Water Quality Act to provide for the protection of public health and the environment. Our regulations (19.15.29.11 NMAC) state the following,

The responsible person shall complete division-approved corrective action for releases that endanger public health or the environment. The responsible person shall address releases in accordance with a remediation plan submitted to and approved by the division or with an abatement plan submitted in accordance with 19.15.30 NMAC. [emphasis added]

Release characterization is the first phase of corrective action unless the release is ongoing or is of limited volume and all impacts can be immediately addressed. Proper and cost-effective remediation typically cannot occur without adequate characterization of the impacts of any release. Furthermore, the Division has the ability to impose reasonable conditions upon the efforts it oversees. **As such, the Division is requiring a workplan for the characterization of impacts associated with this release be submitted to the OCD District II office in Artesia on or before 2/10/18. If and when the release characterization workplan is approved, there will be an associated deadline for submittal of the resultant investigation report. Modest extensions of time to these deadlines may be granted, but only with acceptable justification.**

The goals of a characterization effort are: 1) determination of the lateral and vertical extents along with the magnitude of soil contamination. 2) determine if groundwater or surface waters have been impacted. 3) If groundwater or surface waters have been impacted, what are the extents and magnitude of that impact. 4) The characterization of any other adverse impacts that may have occurred (examples: impacts on vegetation, impacts on wildlife, air quality, loss of use of property, etc.). To meet these goals as quickly as possible, the following items must, at a minimum, be addressed in the release characterization workplan and subsequent reporting:

- Horizontal delineation of soil impacts in each of the four cardinal compass directions. Adsorbed soil contamination must be characterized for the following constituents using the associated laboratory methods: benzene, toluene, ethylbenzene, and total xylenes by either Method 8260 or 8021, total petroleum hydrocarbons by Method 8015 extended range (GRO+DRO+MRO; C₆ thru C₃₆), and for chloride by Method 300. This is not an exclusive list of potential contaminants. Analyzed parameters should be modified based on the nature of the released substance(s). Soil sampling must be both within the impacted area and beyond.
- Vertical delineation of soil impacts. Adsorbed soil contamination must be characterized for the following constituents using the associated laboratory methods: benzene, toluene, ethylbenzene, and total xylenes by either Method 8260 or 8021, total petroleum hydrocarbons by Method 8015 extended range (GRO+DRO+MRO; C₆ thru C₃₆), and for chloride by Method 300. As above, this is not an exclusive list of potential contaminants and can be modified. Vertical characterization samples should be taken at depth intervals no greater than five feet apart. Lithologic description of encountered soils must also be provided. At least ten vertical feet of soils with contaminant concentrations at or below these values must be demonstrated as existing above the water table.
- Nominal detection limits for field and laboratory analyses must be provided.
- Composite sampling is not generally allowed.
- Field screening and assessment techniques are acceptable (headspace, titration, EC [include algorithm for validation purposes], EM, etc.), but the sampling and assay procedures must be clearly defined. Copies of field notes are highly desirable. A statistically significant set of split samples must be submitted for confirmatory laboratory analysis, including the laterally farthest and vertically deepest sets of soil samples. Make sure there are at least two soil samples submitted

for laboratory analysis from each borehole or test pit (highest observed contamination and deepest depth investigated). Copies of the actual laboratory results must be provided including chain of custody documentation.

- Probable depth to shallowest protectable groundwater and lateral distance to nearest surface water. If there is an estimate of groundwater depth, the information used to arrive at that estimate must be provided. If there is a reasonable assumption that the depth to protectable water is 50 feet or less, the responsible party should anticipate the need for at least one groundwater monitoring well to be installed in the area of likely maximum contamination.

- If groundwater contamination is encountered, an additional investigation workplan may be required to determine the extents of that contamination. Groundwater and/or surface water samples, if any, must be analyzed by a competent laboratory for volatile organic hydrocarbons (typically Method 8260 full list), total dissolved solids, pH, major anions and cations including chloride and sulfate, dissolved iron, and dissolved manganese. The investigation workplan must provide the groundwater sampling method(s) and sample handling protocols. To the fullest extent possible, aqueous analyses must be undertaken using nominal method detection limits. As with the soil analyses, copies of the actual laboratory results must be provided including chain of custody documentation.

- Accurately scaled and well-drafted site maps must be provided providing the location of borings, test pits, monitoring wells, potentially impacted areas, and significant surface features including roads and site infrastructure that might limit either the release characterization or remedial efforts. Field sketches may be included in subsequent reporting, but should not be considered stand-alone documentation of the site's layout. Digital photographic documentation of the location and fieldwork is recommended, especially if unusual circumstances are encountered.

Nothing herein should be interpreted to preclude emergency response actions or to imply immediate remediation by removal cannot proceed as warranted. Nonetheless, characterization of impacts and confirmation of the effectiveness of remedial efforts must still be provided to the OCD before any release incident will be closed.

Jim Griswold

OCD Environmental Bureau Chief

1220 South St. Francis Drive

Santa Fe, New Mexico 87505

505-476-3465

jim.griswold@state.nm.us

Weaver, Crystal, EMNRD

From: Weaver, Crystal, EMNRD
Sent: Friday, January 12, 2018 9:12 AM
To: 'Reyna, Jennifer'; Bratcher, Mike, EMNRD; 'Shelly Tucker (stucker@blm.gov)'; NMSLO (Hobbs/Amber Groves); Montoya, Kenda
Cc: Fulks, Brett; Shoemaker, Mike; Aguilar, Leonard; Ryan, Wesley
Subject: RE: Strawberry 7 Fed Com 4H_11 bbls pw_12-27-17

Hello all,

OCD started out as holding on to Initial/Final C-141 until the requested statements and photos were provided by the operators for cases when total volume recovery is mentioned due to having secondary containment that was said to have contained all fluids. Since holding on to the forms and waiting for the requested items above was not working out to be the best way to do things, OCD has decided to now to mark any Initial/Final C-141 that comes in, and is of the above mentioned nature, as an Initial C-141 only and upon receipt of the requested pictures and statements a Final C-141 can be submitted and then reviewed for processing of closure of said release case.

So for this C-141 along with the ones submitted in the recent past for Nermal 4 State 1H (DOR 10/5/17), Beetlejuice 19 Federal (DOR 11/4/17), Grandi 22 2H (DOR 11/14/17), and Lone Tree Draw 13 State COM 8H (DOR 10/24/17) I will go ahead and mark them as Initial C-141 only and process them that way so we get them in the system and off my desk.

If you have any questions or concerns about this change please let either myself or Mike Bratcher know here in the OCD District II Office.

Thank you,

Crystal Weaver

Environmental Specialist
OCD – Artesia District II
811 S. 1st Street
Artesia, NM 88210
Office: 575-748-1283 ext. 101
Cell: 575-840-5963
Fax: 575-748-9720

From: Reyna, Jennifer [mailto:Jennifer.Reyna@dvn.com]
Sent: Wednesday, January 10, 2018 9:36 AM
To: Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>; Weaver, Crystal, EMNRD <Crystal.Weaver@state.nm.us>; 'Shelly Tucker (stucker@blm.gov)' <stucker@blm.gov>
Cc: Fulks, Brett <Brett.Fulks@dvn.com>; Shoemaker, Mike <Mike.Shoemaker@dvn.com>; Aguilar, Leonard <Leonard.Aguilar@dvn.com>; Ryan, Wesley <Wesley.Ryan@dvn.com>
Subject: Strawberry 7 Fed Com 4H_11 bbls pw_12-27-17

Good Morning,

Attached please find the Initial C-141 and GIS Image for the 11 bbls of Produced water release at the Strawberry 7 Fed Com 4H on 12.27.17.

If you have any questions please feel free to contact me.

Thank you,

Jennifer Reyna

Field Admin Support
Production
B-Schedule

Devon Energy Corporation

P.O. Box 250
Artesia, NM 88211
575 746 5588

Confidentiality Warning: This message and any attachments are intended only for the use of the intended recipient(s), are confidential, and may be privileged. If you are not the intended recipient, you are hereby notified that any review, retransmission, conversion to hard copy, copying, circulation or other use of all or any portion of this message and any attachments is strictly prohibited. If you are not the intended recipient, please notify the sender immediately by return e-mail, and delete this message and any attachments from your system.

Weaver, Crystal, EMNRD

From: Reyna, Jennifer <Jennifer.Reyna@dvn.com>
Sent: Wednesday, January 10, 2018 9:36 AM
To: Bratcher, Mike, EMNRD; Weaver, Crystal, EMNRD; 'Shelly Tucker (stucker@blm.gov)'
Cc: Fulks, Brett; Shoemaker, Mike; Aguilar, Leonard; Ryan, Wesley
Subject: Strawberry 7 Fed Com 4H_11 bbls pw_12-27-17
Attachments: Strawberry 7 Fed Com 4H_11 bbls pw_12-27-17 inital C-141.doc; Strawberry 7 Fed Com 4H_11 bbls pw_GIS Image_12.27.17.pdf

Good Morning,

Attached please find the Initial C-141 and GIS Image for the 11 bbls of Produced water release at the Strawberry 7 Fed Com 4H on 12.27.17.

If you have any questions please feel free to contact me.

Thank you,

Jennifer Reyna

Field Admin Support
Production
B-Schedule

Devon Energy Corporation
P.O. Box 250
Artesia, NM 88211
575 746 5588

Confidentiality Warning: This message and any attachments are intended only for the use of the intended recipient(s), are confidential, and may be privileged. If you are not the intended recipient, you are hereby notified that any review, retransmission, conversion to hard copy, copying, circulation or other use of all or any portion of this message and any attachments is strictly prohibited. If you are not the intended recipient, please notify the sender immediately by return e-mail, and delete this message and any attachments from your system.