

~~DISTRICT I~~
1625 N. French Dr., Hobbs, NM 88240
~~District II~~
811 S. First St., Artesia, NM 88210
~~District III~~
1000 Rio Brazos Road, Aztec, NM 87410
~~District IV~~
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: Transwestern Pipeline Company	Contact: Julian Ruiz
Address: 21 Speedway Drive, Gallup NM 87301	Telephone No. 505-863-4104-Cel 505-870-9421
Facility Name: Gallup Comp. Station	Facility Type: Natural Gas Comp. Station

Surface Owner: Transwestern Pipeline Co.	Mineral Owner: Transwestern Pipeline Co.	API No.
--	--	---------

LOCATION OF RELEASE

Unit Letter C	Section 8	Township 15N	Range 17W	Feet from the	North/South Line	Feet from the	East/West Line	County McKinley
------------------	--------------	-----------------	--------------	---------------	------------------	---------------	----------------	--------------------

Latitude N 35.54864

Longitude W 108.66235

NATURE OF RELEASE

Type of Release: Natural Gas Release into Atmosphere	Volume of Release: 3,728.4 MCF	Volume Recovered: None
Source of Release: Station Blow Down Stacks	Date and Hour of Occurrence: 10/27/2017 @ 11:00 AM Hours	Date and Hour of Discovery 10/27/2017 @ 11:00 AM Hours
Was Immediate Notice Given? X Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Cory Smith 505-334-6178 ext. 115 Cell 505-419-2627 10/29/2017 11:45 AM By Phone- e-mail cory.smith@state.nm.us	
By Whom? Julian Ruiz	Date and Hour: 10/27/2017 @ 11:00 Hours <u>Mailed Report</u>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.* N/A

OIL CONS. DIV DIST. 3

NOV 01 2017




Describe Cause of Problem and Remedial Action Taken.*

At 11:00 AM on 10/27/2017 we had a blow down of natural gas into atmosphere through blow down vent stacks at the Gallup Valve site 5008 AM and 5009 Valve, Valve site was blown down do to Maintenance on Pipeline.

Describe Area Affected and Cleanup Action Taken.*

Transwestern Pipeline Company Valve sites 5008AM and 5009. There was no clean up action taken because the natural gas was released into the atmosphere.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		OIL CONSERVATION DIVISION	
Printed Name: Julian Ruiz		Approved by Environmental Specialist: 	
Title: Corrosion Tech. B-Mechanic		Approval Date: <u>2/28/18</u>	Expiration Date:
E-mail Address: : Julian.ruiz@energytransfer.com		Conditions of Approval: 	Attached <input type="checkbox"/> 
Date: 10/27/2017		Phone: 505-863-4104	

* Attach Additional Sheets If Necessary

#NCS 18059396 35

①