

ATTN: VIT CAPTION

1625 French Dr., Hobbs, NM 88240
1301 Grand Avenue, Artesia, NM 88210
1000 Brazos Road, Aztec, NM 87410
1220 Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate District Office in accordance with Rule 16 on back of form

Release Notification and Corrective Action

OPERATOR		<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Name of Company <i>ACOMA OIL CORP.</i>	Contact <i>ROGER STONE</i>		
Address <i>1625 FRENCH DR. SUITE 901 FT. WORTH</i>	Telephone No. <i>432-638-5260</i>		
Facility Name <i>S.J. SARKIS A BTRY 76116</i>	Facility Type <i>OIL FIELD TANK BTRY</i>		
Surface Owner <i>GARY SCOTT (WIFE)</i>	Mineral Owner <i>SARKIS EST.</i>	Lease No. <i>000025</i>	

LOCATION OF RELEASE

Unit/Well	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
<i>A</i>	<i>26</i>	<i>21S</i>	<i>R37E</i>	<i>330'</i>	<i>PNL</i>	<i>990'</i>	<i>FEL</i>	<i>LEA COUNTY</i>

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release <i>PRODUCED OIL</i>	Volume of Release <i>175 BBLs</i>	Volume Recovered <i>5</i>
Source of Release <i>HOLE IN PRODUCTION TANK</i>	Date and Hour of Occurrence <i>4/25/06</i>	Date and Hour of Discovery <i>4/25/06</i>
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully *

Description of Cause of Problem and Remedial Action Taken *

HOLE IN OIL TANK WITH LEAD TO SINK, PICKED UP FREE LIQUID WITH VAC. TRK (VERY STICKY) AND PICKED UP ALL WET DIRT DOWN "6" TO "8" & HAULED TO DISPOSAL. PRACTICE WITH NEW CALICHE

Description of Area Affected and Cleanup Action Taken *

AREA INSIDE TANK BTRY YARD 80' X 80' WAS AFFECTED, VERY SMALL AMOUNT GOT OUT OF BTRY YARD TO NORTH & SOUTH (APPROX 10' X 10') TOOK ALL AFFECTED DIRT TO LANDFILL & REPLACE WITH NEW. TOOK OUT DIRT 8" DEEP

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of their responsibility should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: <i>Roger Stone</i>	Approved by District Supervisor:		
Printed Name: <i>ROGER STONE</i>	Approval Date:	Expiration Date:	
Title:	Conditions of Approval:		
E-mail Address: <i>OILSTONE1461@M.SW.CO.NM</i>	Attached <input type="checkbox"/>		
Date: <i>4-25-06</i>	Phone: <i>432-638-5260</i>		

* Attach Additional Sheets If Necessary

*Acoma-184
facility - #PAC0611639791
incident - #PAC0611639881
application - #PAC0611640145*