

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

RECEIVED  
JUL 11 2018

Form C-141

Revised April 3, 2017

DISTRICT II-ARTESIA O.C.D.  
Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

FAB1819254802 Release Notification and Corrective Action

NAB1819255008

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: Energy Transfer Company (ETC) Field Services, LLC #371183	Contact: Carolyn J. Blackaller, Sr. Environmental Specialist
Address: 600 N. Marienfeld Street, Suite 700, Midland, TX 79701	Telephone No.: (817) 302-9766
Facility Name: Avalon Compressor Station, Eddy County NM	Facility Type: Compressor Station

Surface Owner	State	Mineral Owner	State	API No.
---------------	-------	---------------	-------	---------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
L	20	26S	28E					EDDY

Latitude 32.026252 Longitude -104.117339 NAD83

NATURE OF RELEASE

Type of Release: Natural Gas	Volume of Release: Approx. 376.96 Mcf	Volume Recovered: 376.96 Mcf
Source of Release: Fire	Date and Hour of Occurrence: 4/20/2018 at 9:00am	Date and Hour of Discovery: 4/20/2018 at 9:10am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Olivia, Yu, Environmental Specialist, NMOCD District I	
By Whom? Carolyn J. Blackaller	Date and Hour: 4/20/2018 at 2:44pm CST	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. Not Applicable	

If a Watercourse was Impacted, Describe Fully.\*

Not Applicable

**REVIEWED**

By Olivia Yu at 3:59 pm, Apr 26, 2018

Describe Cause of Problem and Remedial Action Taken.\*

On Friday April 20, 2018 at approximately 9:00am a fire started at the Avalon CS. The cause of the fire was due to a mechanical failure on the 2<sup>nd</sup> stage cylinder of the #6 Compressor Unit (EPN 7107). The mechanical failure caused natural gas to be released at approximately 40psi of pressure out of the ignition source of the compressor unit, which ignites between 700-900°F. This, in turn, auto-ignited into a fire. ETC operations mobilized to the site immediately and shut down the fuel gas. This extinguished approximately 90% of the fire. The Otis Fire Department was dispatched and extinguished the rest of the fire. All of the gas released was consumed by the fire.

Describe Area Affected and Cleanup Action Taken.\*

Not applicable - all gas released was consumed by the fire.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Carolyn J. Blackaller	OIL CONSERVATION DIVISION	
Printed Name: Carolyn J. Blackaller	Approved by Environmental Specialist: <i>oy</i>	
Title: Sr. Environmental Specialist	Approval Date: 4/26/2018	Expiration Date: xx/xx/xxxx

FAB1807457621

nOY181656603

2RP-4851



## ENERGY TRANSFER

April 23, 2018

State of New Mexico Oil Conservation Division, District I  
1625 N. French Dr.  
Hobbs, NM 88240

RE:           **Form C-141 - Release Notification and Corrective Action**  
                  **Energy Transfer Company Field Services, LLC**  
                  **Avalon Compressor Station**

**HOBBS OCD**  
**APR 24 2018**  
**RECEIVED**

To Whom It May Concern,

In accordance with 19.15.29 NMAC, please find enclosed Form C-141 – Release Notification and Corrective Action for the Energy Transfer Company Field Services, LLC - Avalon Compressor Station (CS) fire that occurred on 4/20/2018. The Avalon CS is located in Eddy County, NM. Should you have any questions or require additional information, please do not hesitate to contact me at (817) 302-9766 or at [carolyn.blackaller@energytransfer.com](mailto:carolyn.blackaller@energytransfer.com)

Sincerely,

Carolyn J. Blackaller  
Sr. Environmental Specialist