District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

JUL 1 2 2018

Form C-141 Revised April 3, 2017

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe. NM 87505 Submit 1 Copy to appropriate District Office in **DISTRICT** II-ARTESIA (1910). with 19.15.29 NMAC.

| Salita Fe, INM 87505 | | | | | | | | | | | | | |
|---|--|---|---|--|--|---|--|-------------------------------------|---|--|--------------------------------|---------------------------------------|--|
| Release Notification and Corrective Action | | | | | | | | | | | | | |
| NAB1819453408 | | | | | | OPERATOR | | | | | | | |
| | | | | ion Company 🛭 | | Contact Aaron Kidd, Technical Services Foreman | | | | | | | |
| Address 64 | | | | NM 88210 | Telephone No. 575-748-3371 Facility Type Salt Water Disposal | | | | | | | | |
| Facility Nan | ne Cotton | Draw Unit | 89 | e Sait Water Di | isposai | | | | | | | | |
| Surface Owner Federal Mineral Owner | | | | | | Federal | | | API No. 30-015-31381 | | | | |
| LOCATION OF RELEASE | | | | | | | | | | | | | |
| Unit Letter | Section | Township | Range | Feet from the | North/S | South Line | Feet from the | East/W | Vest Line | County | | | |
| O | 3 | 25S | 31E | | | | | | | Eddy | | | |
| Latitude_32.153094 N_ Longitude103.763271 W_ NAD83 | | | | | | | | | | | | | |
| NATURE OF RELEASE | | | | | | | | | | | | | |
| Type of Relea | ase Oil | | | NAI | UKE | Volume of Release 66 Bbls Volume Recovered 66 Bbls | | | | | | | |
| Source of Release Pipeline below belly of oil tank | | | | | | | Date and Hour of Occurrence | | | Date and Hour of Discovery | | | |
| | | | | | | | | | 6/27/2018 | /27/2018 @ 1:30 AM MST | | | |
| Was Immediate Notice Given? ☐ Yes ☐ No ☐ Not Required | | | | | | If YES, To Whom? NMOCD-Mike Bratcher and Crystal Weaver BLM-Shelly Tucker | | | | | | | |
| By Whom? Mike Shoemaker | | | | | | Date and Hour 6/27/2018 @ 9:20 PM MST | | | | | | | |
| Was a Watercourse Reached? ☐ Yes ☒ No | | | | | | If YES, Volume Impacting the Watercourse. N/A | | | | | | | |
| If a Watercou N/A | irse was Im | pacted, Descr | ibe Fully. | * | | | | | | | | | |
| | erator went | | | n Taken.* aps and upon arriv | al found | a spill inside | the lined contain | ment. U | pon furthe | r inspection | a hole | was found in | |
| Describe Area Affected and Cleanup Action Taken.* Approximately 66bbls of oil was released into the lined SPCC containment ring. A vacuum truck was dispatched and recovered approximately 66bbls of oil from lined containment. All fluid stayed inside the lined SPCC containment. Once fluids were removed the liner was visually inspected by Devon field staff for any pinholes or punctures and none were found. Based on this inspection there is no evidence that the spill fluids left containment. | | | | | | | | | | | | | |
| regulations al public health should their of or the environ | Il operators or the envi operations h nment. In a | are required tronment. The nave failed to | o report and acceptant adequately OCD accep | e is true and comp nd/or file certain r ce of a C-141 repo v investigate and r otance of a C-141 | elease no ort by the emediate | tifications a NMOCD m contaminati | nd perform correct arked as "Final Roon that pose a three | etive acti eport" d eat to gr | ons for rel oes not rel ound wate | eases which ieve the ope r, surface wa | may en rator of ater, hu | ndanger f liability ıman health | |
| | | | | | | | OIL CONSERVATION DIVISION | | | | | | |
| Signature: Tamala J Robison | | | | | | | #1 | | | | | | |
| Printed Name | | | | 1 | Approved by Environmental Specialist Alle Branches | | | | | | | | |
| Title: Field Admin Support | | | | | | Approval Date: 7/13/18 Expiration Date: N/A | | | | | | | |
| E. mail Address: Tamala Pohison@dvn.com | | | | | | Conditions of Approval: | | | | | | | |

FINAL

Phone: 575-748-3371

Date: 6/28/2018

^{*} Attach Additional Sheets If Necessary

Bratcher, Mike, EMNRD

From:

Shoemaker, Mike < Mike. Shoemaker@dvn.com>

Sent:

Wednesday, July 11, 2018 6:19 PM

To:

Bratcher, Mike, EMNRD; Shelly Tucker (stucker@blm.gov)

Cc:

Fulks, Brett; Robison, Tamala

Subject:

Cotton Draw Unit 89 SWD_66 bbls oil_6.27.18

Attachments:

C-1414-3-17_Cotton Draw Unit 89 SWD_66 bbls oil_6.27.2018.doc; Cotton Draw Unit 89

SWD_66 bbls oil_6.27.2018.pdf

Good Afternoon,

Attached please find the Initial C-141 and GIS Image for the 66 bbl oil release at the Cotton Draw Unit 89 SWD on 6.27.18.

If you have any questions please feel free to contact me.

Thank you,

Mike Shoemaker EHS Representative

Devon Energy Corporation

6488 Seven Rivers Highway Artesia, New Mexico 88210 575-746-5566 Office 575-513-5035 Mobile



Confidentiality Warning: This message and any attachments are intended only for the use of the intended recipient(s), are confidential, and may be privileged. If you are not the intended recipient, you are hereby notified that any review, retransmission, conversion to hard copy, copying, circulation or other use of all or any portion of this message and any attachments is strictly prohibited. If you are not the intended recipient, please notify the sender immediately by return e-mail, and delete this message and any attachments from your system.

Bratcher, Mike, EMNRD

From:

Shoemaker, Mike < Mike. Shoemaker@dvn.com>

Sent:

Wednesday, June 27, 2018 9:20 PM

To:

Bratcher, Mike, EMNRD; Weaver, Crystal, EMNRD; Shelly Tucker (stucker@blm.gov)

Cc:

Fulks, Brett

Subject:

Cotton Draw Unit 89 (API #30-015-31381)

Devon had the following release occur at 1:30 AM MST on 06/27/18. The incident is described below.

- 1. Cotton Draw Unit 89 (API #30-015-31381)
 - a. The lease operator went to the site to check pumps and upon arrival found a spill inside the lined containment. Upon further inspection a hole was found in the belly line underneath the oil tank Approximately 66 bbls of oil was released into the lined SPCC containment ring. Approximately 66 bbls was recovered.

A C-141 will be prepared and submitted with GPS coordinates of the area affected.

Thanks,

Mike Shoemaker EHS Representative

Devon Energy Corporation

6488 Seven Rivers Highway Artesia, New Mexico 88210 575-746-5566 Office 575-513-5035 Mobile



Confidentiality Warning: This message and any attachments are intended only for the use of the intended recipient(s), are confidential, and may be privileged. If you are not the intended recipient, you are hereby notified that any review, retransmission, conversion to hard copy, copying, circulation or other use of all or any portion of this message and any attachments is strictly prohibited. If you are not the intended recipient, please notify the sender immediately by return e-mail, and delete this message and any attachments from your system.