District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

## State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised April 3, 2017

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

AUG 2 7 2018

Santa Fe, INIVI 67505												
Release Notification and Corrective Action DISTRICT												
					OP	ERATOR	3	$\boxtimes$	] Initial F	Report	☐ Final Report	
							Contact Thomas Long					
, ,							Telephone No. 505-599-2286					
Facility Name Trunk 2C Pipeline Facility Type Natural Gas Gathering Pipeline												
Surface Owner <b>BLM</b> Mineral Owner <b>B</b>						BLM Serial No. NM 0 015563					015563	
						OF REL		- T	-VF1	83/3	28262	
Unit Letter G	Section 8	Township 26N	Range 10W	Feet from the	North	6outh	Feet from the	East	West	County San Juar		
O	0	2014	1000	1949	Line		1488	Line		Ouri Ouur	•	
Latitude 36.50456 Longitude -108.91551 NAD83												
NATURE OF RELEASE												
Type of Release: Natural Gas and Natural Gas Liquids						Volume of Release Estimated 5-7 Barrels of Condensate/Water  Volume Recovered None				None		
Source of Release: Suspected Internal Corrosion						The second secon	Hour of Occur at 10:30 a.m.	The second secon		Hour of Discovery at 10:30 a.m.		
Was Immediate Notice Given?						If YES, To Whom? :Notification Cory Smith/Vanessa Fields – NMOCD;						
☐ Yes ☐ No ☒ Not Required							Whitney Thomas					
Required												
By Whom? Thomas Long						Date and Hour August 10, 2018 @ 8:37 a.m.						
Was a Watercourse Reached?						If YES, Volume Impacting the Watercourse.						
☐ Yes ⊠ No												
If a Watercourse was Impacted, Describe Fully.*												
Describe Cause of Problem and Remedial Action Taken.* On August 9, 2018 an Enterprise technician discovered a release of natural gas on the Lateral 2C-40 pipeline. The pipeline was isolated, depressurized, locked out and tagged out.												
Describe Area Affected and Cleanup Action Taken.* Repairs and remediation are in progress. The contaminant mass will be removed by												
mechanical excavation. A third party corrective action report will be included with the "Final" C-141.												
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases												
which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not												
relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to												
ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.												
							OIL CONSERVATION DIVISION					
Simple file												
Signature: JW ( Turk)						Approved by Environmental Specialist						
Printed Nan	ne: Jon E. F	/	Approved by Environmental Specialist:									
Title: Director, Field Environmental						Approval Date: \\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\						
E-mail Address: jefields@eprod.com						Conditions of Approval:				Attache	d $\square$	

Date: 8/2/18 Phone: (713) 381-6684

\* Attach Additional Sheets If Necessary

NCS 1829551947