

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

705252 L  
Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

**OPERATOR**

☐ Initial Report ☒ Final Report

Name of Company CHEVRON USA INC.	Contact Danny Lovell
Address P.O. Box 1949 Eunice NM. 88231	Telephone No. 505-394-1242 (office), 505-390-0866 (cell)
Facility Name- B.F. Harrison #1 BTY	Facility Type - Production

Surface Owner- JEAN SALSMAN	Mineral Owner - State of New Mexico	Lease No.
-----------------------------	-------------------------------------	-----------

**LOCATION OF RELEASE**

Unit Letter C	Section 9	Township 23S	Range 37E	Feet from the	North/South Line	Feet from the	East/West Line	County Lea
								5.10.06

86'

Latitude 32 19.5' Longitude 103 10.3'

**NATURE OF RELEASE**


Type of Release-OIL AND PRODUCED WATER	Volume of Release 1/2 BO, 15 BW	Volume Recovered- 8 BW
Source of Release- 2 1/2" STEEL FLOWLINE	Date and Hour of Occurrence- 4/27/06	Date and Hour of Discovery 4/27/06 @ 8:30 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Pat Caperton	
By Whom? Larry Williams	Date and Hour 4/27/06 @ 2:00 P.M.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\* INTERNAL CORROSION ON STEEL FLOWLINE INSIDE BATTERY YARD. REPLACE FLOWLINE

Describe Area Affected and Cleanup Action Taken.\* FLUID WAS CONTAINED WITHIN BATTERY YARD. STANDING FLUID WAS VACUUMED UP. DEPTH TO GW=90-100'.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Larry Williams	Approved by District Supervisor:	
Title: HES Champion	Approval Date:	Expiration Date:
E-mail Address: lcwl@chevrontexaco.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 5/01/06 Phone: 505-394-1237		

\* Attach Additional Sheets If Necessary

Facility - FPAC0613034739  
Incident - FPAC0613034845  
Application - FPAC0613035071