

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

### Release Notification and Corrective Action

#### OPERATOR

☒ Initial Report ☐ Final Report

Name of Company YATES PETROLEUM CORPORATION	OGRID Number 25575	Contact SHERRY BONHAM
Address 104 S. 4 <sup>TH</sup> STREET	Telephone No. 505-748-1471	
Facility Name CONTINENTAL API FEDERAL I BATTERY	API Number 30-025-20428	Facility Type BATTERY
Surface Owner FEDERAL	Mineral Owner FEDERAL	Lease No. NM-77063

#### LOCATION OF RELEASE

Unit Letter C	Section 28	Township 23S	Range 32E	Feet from the 660	North/South Line NORTH	Feet from the 1980	East/West Line WEST	County LEA
------------------	---------------	-----------------	--------------	----------------------	---------------------------	-----------------------	------------------------	---------------

Latitude 32.28088 Longitude 103.68117

1 RP-895

#### NATURE OF RELEASE

Type of Release PRODUCED WATER	Volume of Release 8 B/PW	Volume Recovered 0 B/PW
Source of Release 1. POWER FAILURE ON WATER DISPOSAL PUMP (5BBL P/W) 2. TRUCK DRIVER FAILED TO KEEP TRACK OF WATER LEVEL IN TANK AND RESULTED IN OVERFLOW (3 BBL P/W)	Date and Hour of Occurrence 5/8/06 AM	Date and Hour of Discovery 5/8/06 AM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? N/A	
By Whom? N/A	Date and Hour N/A	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* 1. POWER FAILURE ON WATER DISPOSAL PUMP CAUSING TANK TO OVERFLOW. AFTER PUMPER RECEIVED ALARM, PUMPER DROVE TO LOCATION AND STARTED PUMP. 2. TRUCK DRIVER FAILED TO KEEP TRACK OF WATER LEVEL IN TANK RESULTING IN OVERFLOW. DRIVER CLOSED VALVE.		
Describe Area Affected and Cleanup Action Taken.* 1. AN APPROXIMATE 100 SQUARE FEET AREA NORTHWEST OF THE PUMPING UNIT WAS IMPACTED BY RELEASE OF PRODUCED WATER. EXCAVATE AND REMOVE IMPACTED MATERIALS AND REPLACE WITH CLEAN MATERIAL. 2. AN APPROXIMATE 120 SQ. FT. AREA WITHIN BERM IMPACTED. AREAS TO BE EVALUATED. SITE RANKING: 0		

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

#### OIL CONSERVATION DIVISION

Signature: <i>Sherry Bonham</i>	Approved by District Supervisor:	
Printed Name: Sherry Bonham		
Title: Environmental Regulatory Agent Trainee	Approval Date:	Expiration Date:
E-mail Address: sherryb@ypenm.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: Friday, May 19, 2006	Phone: 505-748-1471	

\* Attach Additional Sheets If Necessary

facility - FPAC0614446910  
incident - FPAC0614447019

application - FPAC0614447264