

24 May 2006

Mr. Larry Johnson, Environmental EngineerNew Mexico Oil Conservation Division1625 North French DriveHobbs, New Mexico 88240

Re: Initial C-141 Chesapeake Energy NMFU Federal #1 – Reference #169058 cc¹⁰¹ 3 UL-P, Section 23, Township 20 South, Range 38 East

Dear Mr. Johnson:

Environmental Plus, Inc. (EPI), on behalf of Mr. Bradley Blevins, Chesapeake Energy Corporation (Chesapeake), submits the attached New Mexico Oil Conservation Division (NMOCD) form C-141 for the above-referenced leak site, located on land owned by G.P. Sims.

The site is located approximately 9 miles north of Eunice, New Mexico (reference *Figure 1*). Information obtained from the New Mexico Office of the State Engineer's website and a United States Geological Survey (USGS) database indicates there are no water supply wells within a 1,000-foot radius of the release site. However, there are two water supply wells located within a 1.0-mile radius of the release site (reference *Figure 2*). Groundwater level data indicates an average depth to water of approximately 55 feet below ground surface (reference *Table 1*). The attached site information and metrics form ranks the site in accordance with the <u>NMOCD Guidelines for Remediation of Leaks, Spills and Releases (August 13, 1993)</u>.

Approximately 202 barrels of oil was released due to the structural integrity of the tank failing, with 120 barrels recovered.

Should you have any questions or concerns please feel free to contact me at (505) 394-3481 or via email at <u>iolness@envplus.net</u> or Mr. Bradley Blevins at (505) 391-1462 ext. 6224 or via e-mail at <u>bblevins@chkenergy.com</u>. All official communication should be addressed to:

> Mr. Bradley Blevins Chesapeake Energy P.O. Box 190 Hobbs, New Mexico 88240

Sincerely,

1


٩,


ENVIRONMENTAL PLUS, INC.


en

Iain Olness, P.G. Technical Manager

 cc: Bradley Blevins, Chesapeake Energy – Hobbs, NM Curtis Blake, Chesapeake Energy – Hobbs, NM Harlan Brown, Chesapeake Energy – Oklahoma City, OK G. P. Sims, Landowner File







۰,

TABLE 1

ţ,

۰.

Well Data

Chesapeake Energy NMFU Federal #1 (Ref. #160058)

Well Number Diversion ^A	Diversion ^A	Owner	Use	Twsp	Rng	Sec q q q	Latitude	Longitude	Date Surface Measured Elevation ^B	Surface Elevation ^B	Depth to Water (ft bgs)
L 10055	0	DALLAS MCCASLAND	EXP	20S	38E	24 111	N32° 33' 43.29"	N32° 33' 43.29" W103° 06' 36.98"	13-Dec-88	3,570	30
L 10055	3	DALLAS MCCASLANE	STK	20S	38E	24 111	N32° 33' 43.29"	W103° 06' 36.98"	13-Dec-88	3,570	30
L 083102 L 072392 U 07980	21-12 12-12 12-12-12	ALTON HOWSE I/O. COURSEY MILLARD/DECK	NSTK DOM DOM	20S 20S 20S	38E 38E 38E	13-21/1 14 - 2,1 26 - 3,4 13 - 1,431.5	NB2°34"35:57" N32°34"35:67" N32°32"11152"	W103*06/37/24%	10-10-80 16-1an-54 05-10n-78 31-1an-96	-3,569 -3,585 -3,560 -1,3,560	-142

* = Data obtained from the New Mexico Office of the State Engineer Website (http://iwaters.ose.state.nnn.us.700)/iWATERS/wr_RegisServlet) and the USGS website (http://waterdata.usgs.gov/nwis).

 $^{A} = in acre feet per annum$


 $^{\rm b}={\rm E}{\rm levation}$ interpolated from USGS topographical map based on referenced location.

STK = Livestock Watering DOM = 72-12-1 Domestic One Household

EXP = Exploration

quarters are 1=NW, 2=NE, 3=SW, 4=SE; quarters are biggest to smallest

Shaded areas indicate well locations not shown on Figure 2




.

۰.

Photograph #1 – Lease sign.




Photograph #2 - Looking southwesterly.



•. ',

Photograph #3 - Looking south.



Photograph #4 - Looking southwesterly.

	•	Incident I	Date:	NMOCD N	otified:		
	A	21 May 20		22 May 200			
Ch	esapeake		,00	22 may 200	•		
	tion and Metrics						
Site: NMFU Fe		<u> </u>	Assigned Site	Reference : #16	0058		
	hesapeake Energy		Assigned Site	Kelerence . #10	0038		
	: 1616 West Bender			·····			
	ss: P.O. Box 190		. <u></u>				
	Hobbs, New Mexico	88240					
	: Bradley Blevins	00210					
Representative		-1462 ext. 622					
Telephone:	(303) 391	1102 0.40. 021		•			
	eleased (bbls): 202	(Ballina	Recov	ered (bbls): 120)		
	>25 bbls: Notify NM	OCD verbally y					
 				500 mcf Natural			
5-25 b	bls: Submit form C-141 wi	thin 15 days (A	Also applies to un	authorized release	es of 50-500 mcf Natural Gas)		
Leak, Spill, or	Pit (LSP) Name: NMFU	Federal #1					
	amination: Tank Battery						
	.e., BLM, ST, Fee, Other				·		
	ns: 57 feet by 28.5 feet; 2		eet;10 feet by 50	feet; 2 feet by 5	feet		
	550 ft^2 ; ~ 600 ft^2 ; ~ 50 ft^2 ;	$\sim 10 \text{ ft}^2$					
	ference Point (RP):			<u> </u>			
	nce and direction from F	<u>RP:</u>					
Latitude: N 32							
	103° 06' 46.21"						
	e mean sea level: 3,573	feet					
	th Section Line: 660				······		
	Section Line: 660						
	or 1/41/4: SE1/4 of the SE	1/4	Unit Letter	: P			
Location-Secti							
	nship: 20 South			·····			
Location- Ran	ge: 38 East				······		
					·····		
	body within 1000 ' radiu			······			
	r wells within 1000' radi						
	ater wells within 1000' r						
	upply wells within 1000'						
	nd surface to groundwat		teet		······································		
	mination (DC): unknow			<u> </u>	·····		
	ndwater (DG – DC = DtC						
	Groundwater <50 feet: 20 points		ellhead Protect		3. Distance to Surface Water Body		
	50 to 99 feet: 10 points		om water source, estic water sourc		<200 horizontal feet: 20 points		
II Depui to Gw	50 to 99 feet. To points		om water source,		200-1000 horizontal feet: 10 points		
	>100 feet: 0 points		estic water source,		>1000 horizontal feet: 0 points		
Site Rank (1+2-							
Total Site Ranking Score and Acceptable Concentrations							
Parameter	>19		10-19		0-9		
Benzene	10 ppm		10 ppm		10 ppm		
BTEX	50 ppm		50 ppm		50 ppm		
TPH	100 ppm		1,000 pp		5,000 ppm		
100 ppm field	VOC headspace measurer	nent may be si	ubstituted for lab	analysis			

<u>District I</u> 1625 N. French E <u>District II</u> 1301 W. Grand A <u>District III</u> 1000 Rio Brazos <u>District IV</u> 1220 S. St. Franc	venue, Artes Road, Aztec,	ia, NM 88210 NM 87410		I	State of New Mexico Energy Minerals and Natural Resources Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505				Submit Distr	Revis 2 Co fict Of with	F	
•		F	Release	e N	otificatio	n a	nd Correc	tive Action	1			
					OPERAT	OR		🛛 Initi	al Rej	port]
Name of C	Company	: Chesape	ake Ene	erg	y		Contact: Bra	adley Blevins				
Address:	P.O. Box	190					Telephone N	No.: (505) 391	1-1462	2 ext.	6224	ŀ
Facility Na	ame: NN	/IFU Feder	al #1				Facility Typ	e: Battery		-		
Surface O	wner: G	. P. Sims			Mineral (Dwn	er: Federal		Α	PI No	.: 3()
					LOCATIO	DN C	OF RELEAS	E				
Unit Letter PSection 23Township 20SRange Range				F	Feet from the 660	Noi	th/South Line South	Feet from the 660	East	/West L East	ine	
	55'	Lat	itude: <u>1</u>	<u>N 3</u>			ongitude: <u>W</u> F RELEASE	/ 103° 06' 46.2	<u>21"</u>			L
Type of Release: Crude oil						Volume of Release: 202 bbls		Volume Reco		Recov	e	
Source of Release: Battery							Date and Hour of Occurrence:			ate and		
Was Immedia			Yes 🗌	No	🗌 Not Requ	iired					106 <u>a</u>	1
By Whom? B								Ir: May 22, 2006				_
Was a Water	course Kea		Yes 🖂 I	No			Not Applicabl	ne Impacting the e	e Water	course:		

If a Watercourse was Impacted, Describe Fully.* Not Applicable

Depth to Groundwater: ~55 feet

Describe Cause of Problem and Remedial Action Taken.* Approximately 202 bbls was released due to the structural integrity of the tank battery failing. The tank was isolated and scheduled to be replaced.

Describe Area Affected and Cleanup Action Taken.* Approximately 2,300 square-feet of surface area was impacted by the release. The tank was isolated and scheduled to be replaced.

Form C-141

side of form

Final Report

County

Lea

Revised October 10, 2003

with Rule 116 on back

Submit 2 Copies to appropriate

API No.: 3002533836

Volume Recovered: 120 bbls

Date and Hour of Discovery:

21 May 2006 @ a.m.

District Office in accordance

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Fradby Blanning		<u>SERVATION DI</u>	VISION
Printed Name: Bradley Blevins	Approved by District Sup	ervisor:	
Title: Field Supervisor	Approval Date:	Expiration	Date:
E-mail Address: bblevins@chkenergy.com Date: 5 - 25 - 06 Phone: (505) 391-1462 ext. 6224	Conditions of Approval:		Attached 🗌

Jacility - fPACOG 15628434 Weident - nPACOG 15628674 application - pPACOG 15628674