

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	ROBERT H. FORREST JR OIL LLC	Contact	ROBERT H. FORREST, JR.
Address	609 ELORA DR, CARLSBAD, NM 88220	Telephone No.	505-885-6870, Cell 505-302-1011
Facility Name	EXXON FEDERAL #2 SWD	Facility Type	SWD

Surface Owner	Mineral Owner	Lease No.	NMNM16353
---------------	---------------	-----------	-----------

LOCATION OF RELEASE API#3002S2820200^{EC}

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
K	27	24S	32E	1980	SOUTH	1980	WEST	LEA

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release	SWD OVERFLOWED	Volume of Release	10 bbl.	Volume Recovered	8 bbl.
Source of Release	EXXON FEDERAL #2	Date and Hour of Occurrence	3/1/06	Date and Hour of Discovery	3/1/06
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	BLM		
By Whom?	ROBERT H. FORREST, JR.	Date and Hour	3/1/06 12NOON		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse:			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

AN ELECTRICAL STORM HIT AND POWER WAS OFF AT THE SWD. THE TANK OVERFLOWED AND APPROXIMATELY 10 BBLs. OF PRODUCED WATER RAN INTO THE DIKED AREA.

Describe Area Affected and Cleanup Action Taken.*

A VACUUM TRUCK WAS SENT OUT TO THE LEASE AND SUCKED UP THE FLUID. 452 YARDS OF SOIL WERE REMOVED AND DISPOSED OF PROPERLY AT CRI

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Robert H. Forrest Jr.</i>	OIL CONSERVATION DIVISION	
Printed Name: ROBERT H. FORREST JR.	Approved by District Supervisor: <i>Carl [Signature]</i>	
Title: owner/operator	Approval Date: 5-30-06	Expiration Date: ENVIRONMENTAL ENGINEER
E-mail Address: BFORREST@WARPDRIVEONLINE.COM	Conditions of Approval: delineate chloride impact.	Attached <input type="checkbox"/>
Date: 5/23/06	Phone: 505 302-1811	

* Attach Additional Sheets If Necessary

incident - n PAC0615629557
application - p PAC0615629799

Bobby Forrest

To:
Subject:

OIL CONSERVATION DIVISION
ATTENTION : PAUL SHEELEY

TO: PAUL SHEELEY

FROM: ROBERT H. FORREST JR.

DATE: 5/22/06

EXXON A FEDERAL #2

LEASE: NMNM16353

K-27-24S-32E

CLEAN UP PLAN

- (1) ALL OF THE FLUIDS WERE REMOVED FROM THE DIKE AREA WITH A VACUUM TRUCK AND DISPOSED OF PROPERLY.
- (2) ROADRUNNER ENVIRONMENTAL DUG UP 72 YARDS OF SOIL AND HAULED IT TO CONTROLLED RECOVERY INC.
- (3) B AND R TRUCKING USED A TRACKHOE AND FIVE BELLYDUMPS TO HAUL NINETTEN LOADS OF SOIL TO CONTROLLED RECOVERY INC. EACH LOAD WAS ROUGHLY TWENTY YARDS WHICH TOTALLED 380 YARDS.
- (4) ALL OF THE EQUIPMENT WAS MOVED TO THE NORTH SIDE OF THE PIT. IT WAS BLM APPROVED. THE GROUND WAS LEVELLED AND A SIX INCH SANDPAD WAS LAID DOWN BEFORE THE PLASTIC LINER WAS INSTALLED. AFTER THE PLASTIC WAS LAID DOWN ANOTHER SIX INCH SANDPAD WAS LAID ON TOP ON TOP OF IT. THE PLASTIC LINER COVERS ALL BACKS. THE 300 BARRELL WATER TANK PLUS AND ADDITIONAL 300 BARRELL WATERTANK WAS SAT ON THE PAD. THE EXTRA TANK WAS INSTALLED TO KEEP THE DISPOSAL FROM RUNNING OVER.
- (5) THE DUG OUT PIT AREA WILL BE FILLED WITH SOIL FROM THE LOCATION ON WHICH IT SITS.

Robert H. Forrest Jr.
ROBERT H. FORREST JR.
OWNER/OPERATOR

Paul Sheeley
ENVIRONMENTAL ENGINEER

