District 1
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1200 S. St. Francis Dr., Santa Fe, NM 87505

## State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe. NM 87505 Form C-141 Revised October 10, 2003

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

1220 S. St. Ptall	LIS Dr., Sailla	re, MINI 67303		Sa	ınta F	e, NM 875	05						
Release Notification and Corrective Action													
			PERA	ATOR Initial R					$\boxtimes$	Final Report			
Name of Company OGRID Number													
Yates Petroleum Corporation 25575 Address						Robert Asher Telephone No.					232	25262720	
104 S. 4 <sup>TH</sup> Street						505-748-1471					<i>L</i> .		
Facility Nat						Facility Type				8 1920	VB.	d din	
Amanda AMN Federal #1 30-025-31947						Battery					Tu.	1000 CO	
Surface Ow	ner			Mineral C	)wner				Lease I	VΦ. <del>***</del>	1 70	SC HOPOS	
Federal			Federal			NM-770			002	S. Carlotte			
Unit Letter Section Township Range Feet from the North/South Line Feet from the East/West Line County													
Unit Letter Section Township F 11 23S			Range 32E				North 1650 East wo			ine County Explication 6819			
Latitude 32,32016 Longitude 103.64814													
NATURE OF RELEASE													
Type of Rele Crude Oil &		/atau		Volume of Release Volume I				Recovered					
Source of Re		vater				4 B/O & 4 B/PW  Date and Hour of Occurrence			0 B/O & 0 B/PW  Date and Hour of Discovery			у	
Water Tank	<b>\1</b> -4! /	310				6/14/2006 - AM				6/14/2006 - AM			
Was Immedi	ate Notice (		equired	If YES, To Whom?									
By Whom? N/A				Date and Hour N/A									
Was a Watercourse Reached?  ☐ Yes ☒ No						If YES, Volume Impacting the Watercourse.							
	urse was Im	pacted, Descr		N/A									
N/A Describe Cause of Problem and Remedial Action Taken.*											<del></del>		
Valve on 210 BBL Water Tank was left open to 500 BBL tank, causing smaller tank to overflow. Spilled fluids did not get out											f berm.		
Describe Area Affected and Cleanup Action Taken.* An approximate area of 30' X 20'. Valve shut when discovered. No standing fluids to recover. Depth to Ground Water: >100'; Wellhead Protection													
Area: No: Distance to Surface Water Body: >1000'; SITE RANKING IS 0. Requesting final closure based on fluid conta											ent insi	de berm and	
site ranking.													
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to												rules and	
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability													
should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other													
federal, state, or local laws and/or regulations.												my onici	
Signature: Cald (1)						OIL CONSERVATION DI					ION		
Printed Name	e: Robert A	sher				Approved by District Supervisor:							
Title: Environmental Regulatory Age			it ,			Approval Date: Expiration		Date:	Date:				
E-mail Address: boba@ypcnm.com			(			Conditions of Approval:			Attach	Attached			
Date: Thursd	ay, June 22.	2006	Phone: 505-748-1471							Underlied [			
Attach Addi	tional Shee	ts If Necess	,10-	171					) // 1	H=1200			
MCC	tent	: -nf	40 . E 11	14					1P+	7433			
applie	Attach Additional Sheets If Necessary  Machine - PACOG17354876  application-PACOG17355443												