1625 N. French Dr., Hobbs, NM 88240

District II 1301 W. Grand Avenue, Artesia, NM 88210

District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

District III 1000 Rio Brazos Road, Azrec, NM 87410

FROM-CONCHO

+4326854399

State of New Mexico Energy Minerals and Natural Resources

> Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

T-202 P.02/02 F-154

FORM C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 of form side of form

			Kei	ease Mounc	:auo		rrecuve A	rcnon)				
						OPERA'			🛛 Initi	al Report	Final R	epo:	
Name of Company COG OPERATING LLC						Contact Diane Kuykendall							
Address 550 W. Texas, Suite 1300 Midland, TX 79701 Facility Name Jalmat Yates Unit #7						Telephone No. 432-683-7443 Facility Type Gas Well							
racinty Mar	de lamai	Tales Omi	#/			гасшіў Гур	e Gas Well						
Surface Owner Clay Osborne Mineral Owner						Lease No. 301048							
				LOCA	N OF REI	LEASE	APIT	#3002	5097	470000			
Unit Letter Section Township Range Feet from the North									West Line County				
0	12	25S	36E	990		South	1650	1 1	East		Lea		
Takinda Ta-19-3-												 -	
			La	titude		Longitud	e						
	Type of Release Produced Water & Oil Volume of Release 11 bbls Volume Recovered None												
		Volume of Release 11 bbls Volume Recovered None											
Source of Release Wellhead connection										Hour of Discovery			
Was Immediate Notice Given?						If VRS To Whom?							
✓ Yes ☐ No ☐ Not Required						Hopes NMOCD (temate that answered phone)							
By Whom? Boyd Chesser						Date and Hour 6/12/2006 2:00 pm							
Was a Watercourse Reached? ☐ Yes ☑ No						If YES, Volume Impacting the Watercourse.							
If a Watercou	ne was Imp	ected Describ	be Fully.					,		A4567	697		
									/^	2	1077		
									(8	A.L	F. 1		
									3037	~ % %	A B		
Describe Cau									53	16,0%	उ		
If a Watercourse was Impacted, Describe Fully,* Describe Cause of Problem and Remedial Action Taken.* The cable rod rotator broke and wrapped around the wellhead and broke off connection causing leak. Fixed wellhead Cause of Problem and Remedial Action Taken.*													
									23/	•			
Describe Arca	Affected an	d Cleanup A	ction Tak	en *					· /c	Cx	- 100 K		
Release of 1 t	oble oil and l	0 bbls water	on location	on and all was abso	orbed i	nto ground. Fi	xed the wellhead	d and cle	aned locari	on with Back	hoc and picked	រោ	
contaminated	soil,										-	•	
			•										
I hereby certif	fy that the in	formation giv	en above	is true and comple	ete to t	he best of my l	cnowledge and u	ınderstan	d that pura	uant to NMO	CD rules and		
regulations at	t operators at or the enviro	c required to nment. The s	report an	d/or file certain re e of a C-141 repor	icase I t hv th	ionfications and R NMOCD ma	d perform correct rked as "Final R	ctive action	ons for rele see not relia	ases Which n	nay endanger		
should their o	perations hav	e failed to ac	lequately	investigate and re-	media	te contaminatio	n that pose a thr	cat to gr	ound water.	surface water	er, human healti	3	
or the environ	ment. In add	lition, NMO(CD accep	tance of a C-141 n	eport d	loes not relieve	the operator of	responsil	bility for co	mpliance wi	th any other		
federal, state, or local laws and/or regulations.						OIL CONSERVATION DIVISION							
= + = 1/1/						OPP DOTABLE VILLOT DIVIDION							
Signature: Signature:						Annual Division							
Printed Name: Diane Kuykendall						Approved by District Supervisor:							
Title: Regulatory Analyst						Approval Date: Expiratio			expiration [i Date:			
E-mail Address: dkuykendall@conchoresources.com						Conditions of Approval:				Attached			
												Date: 6/13/200	
Atrach Addin	onal Sheets	II Necessa	ry pl	Kylis 124Da	1 -	,							
	mac	dent-	nPl	AE06199 PAC06 960	140	760							
	anno	ication	· M, -	OPACOG	199	141423	>						
	THE	annin	14	010	• /								
		TYP	1 #	400			•						