

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised March 17, 1999

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Duke Energy Field Services	Contact Paul Mulkey
Address 11525 West Carlsbad Hwy, Hobbs, NM 88240	Telephone No. 505.397.5716
Facility Name Lovington 4" C-1 Line – Release Site 9	Facility Type Natural Gas Pipeline

Surface Owner Mr. Darr Angell (dba "U-Bar Ranch")	Mineral Owner	Lease No.
--	---------------	-----------

34'

LOCATION OF RELEASE

Unit Letter L	Section 24	Township 17S	Range 36E	Feet from the South Line 2100	Feet from the West Line 330	Latitude 32° 49' 08.74" N	Longitude 103° 18' 55.50"W	County: LEA
------------------	---------------	-----------------	--------------	-------------------------------------	-----------------------------------	---------------------------------	-------------------------------	----------------

NATURE OF RELEASE

Type of Release Sour Natural Gas and associated components	Volume of Release Unknown	Volume Recovered NA
Source of Release 4" Steel pipeline	Date and Hour of Occurrence	Date and Hour of Discovery
Was Immediate Notice Given? Historical Site <input type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. NA	
If a Watercourse was Impacted, Describe Fully.* NA		
Describe Cause of Problem and Remedial Action Taken.* Corroded pipe. Line repair clamps installed.		
Describe Area Affected and Cleanup Action Taken.* Area = 7074-ft ² (733.1-ft perimeter). Ground water occurs at ~50-ft bgs. The site rank is 20 points. Contaminated soil above the site remedial goals will be excavated and disposed of by Environmental Plus, Inc., Eunice, NM. Remedial Goals: TPH 8015m = 100 mg/Kg, BTEX = 50 mg/Kg, Benzene = 10 mg/Kg, Chloride = 250 mg/Kg, and Sulfate = 600 mg/Kg.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature:	OIL CONSERVATION DIVISION	
Printed Name: Paul Mulkey	Approved by District Supervisor:	
Title: Construction & Maintenance Supervisor	Approval Date:	Expiration Date:
Date: 7-29-02 Phone: 505.397.5716	Conditions of Approval:	Attached <input type="checkbox"/>

Attach Additional Sheets If Necessary

RP#995
facility - NPAC0621456255
incident - NPAC0621456321
application - NPAC0621456397