District I 1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Revised October 10, 2003 Submit 2 Copies to appropriate District Office in accordance

Form C-141

with Rule 116 on back side of form

Release Notification and Corrective Action **OPERATOR** Initial Report Final Report Contact Toni Collier Name of Company ExxonMobil Telephone No. 281-654-1133 Address P.O. Box 4358, Houston, TX 77210 Facility Name JD Knox TB #3 Facility Type Tank Battery Mineral Owner New Mexico Lease No. 4185 LOCATION OF RELEASE Township Feet from the North/South Line Feet from the East/West Line Section Range County

Surface Owner New Mexico Unit Letter 10 36E Lea 218 **Latitude** N32.29.820 **Longitude** W103.14.953 30 NATURE OF RELEASE Volume of Release 40.2 Bbls Type of Release Oil Volume Recovered 30 Bbls Source of Release Tank Date and Hour of Occurrence Date and Hour of Discovery 7/13/06 8:00AM 7/13/06 8:00 am If YES, To Whom? Was Immediate Notice Given? Pat Caperton By Whom? Shelby Pennington Date and Hour 7/13/06 1:30PM Was a Watercourse Reached? If YES, Volume Impacting the Watercourse. ☐ Yes ☒ No If a Watercourse was Impacted, Describe Fully.* Describe Cause of Problem and Remedial Action Taken.* Leak on 400 bbl tank due to internal corrosion. Free Fluid was recovered. Describe Area Affected and Cleanup Action Taken.* Most of the leak was contained in the firewall. A delineation plan and remediation plan will be submitted for approval. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. OIL CONSERVATION DIVISION Signature: Approved by District Supervisor: Printed Name: Timothy O. Cagle Title: Compliance Supervisor Approval Date: **Expiration Date:** E-mail Address: Timothy.O.Cagle@exxonmobil.com Conditions of Approval: Attached 7/26/06 Phone: 281-654-1001

Attach Additional Sheets If Necessary

aculty - fPACO621532665 incident - n PACO621532746 Polication - pPACO621532881