

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report


Name of Company Yates Petroleum Corporation	OGRID Number 25575	Contact Robert Asher
Address 104 S. 4 TH Street	API Number 30-025-33354	Telephone No. 505-748-1471
Facility Name April APZ State #1	Facility Type Flow Line	
Surface Owner State	Mineral Owner State	Lease No. V-3652

LOCATION OF RELEASE

Unit Letter A	Section 12	Township 23S	Range 32E	Feet from the 330	North/South Line North	Feet from the 330	East/West Line East	County Lea
------------------	---------------	-----------------	--------------	----------------------	---------------------------	----------------------	------------------------	---------------

Latitude 32.32549 Longitude 103.62033

NATURE OF RELEASE

Type of Release Crude Oil & Produced Water	Volume of Release 3 B/O & 160 B/PW	Volume Recovered 0 B/O & 120 B/PW
Source of Release Transfer Pump	Date and Hour of Occurrence 8/4/2006 - AM	Date and Hour of Discovery 8/4/2006 - AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Pat Caperton, OCD District I	
By Whom? Mike Stubblefield, Yates Petroleum Corporation	Date and Hour 8/4/2006, 3:20 PM by e-mail	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* Nipple on discharge side of pump rusted, causing a hole. Shut in valve on flow line and made repairs.		
Describe Area Affected and Cleanup Action Taken.* An approximate area of 15' X 250', Soils to be excavated. Area to be evaluated. Depth to Ground Water: >100'; Wellhead Protection Area: No; Distance to Surface Water Body: >1000'; SITE RANKING IS 0. .		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOC marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOC acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Robert Asher	Approved by District Supervisor:	
Title: Environmental Regulatory Agent	Approval Date:	Expiration Date:
E-mail Address: boba@ypcnm.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: Thursday, August 17, 2006	Phone: 505-748-1471	

* Attach Additional Sheets If Necessary

incident - NPAC0624024550
application - pPAC0624024698

RP# 1011