

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	Chevron	Contact	Larry D. Ridenour
Address	HCR 60 Box 423 Lovington, NM 88260	Telephone No.	505-396-4414
Facility Name	Vacuum Glorietta West Unit Sat I	Facility Type	Injection facility

Surface Owner	State	Mineral Owner	State	Lease No.	B-2317
---------------	-------	---------------	-------	-----------	--------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
C	36	17-S	34-E					Lea

122'

Latitude 32 deg 47 min 45.1 sec Longitude 103 deg 30 min 54.7 sec

NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	80 bbls	Volume Recovered	79 bbls
Source of Release	injection trunkline	Date and Hour of Occurrence	8/31/06 8:30 AM	Date and Hour of Discovery	8/31/06 9:00 AM
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Pat Caperton		
By Whom?	Larry Ridenour	Date and Hour	8/31/06 1:25 PM		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*



Internal corrosion.

Fitting replaced with stainless steel spool piece.

Describe Area Affected and Cleanup Action Taken.*

Leak occurred in valve box and was contained in the valve box. Vacuum truck picked up all the fluid. Contaminated dirt removed and sent to land farm.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Larry D. Ridenour	Approved by District Supervisor: 	
Title: Operations Representative	Approval Date: 9.12.06	Expiration Date:
E-mail Address: LRidenour@Chevron.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 8/31/06	Phone: 505-396-4414 x102	

* Attach Additional Sheets If Necessary

Facility - PPAC0625530723
Incident - PPAC0625530851
Application - PPAC0625530973

RP#1031