

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form


Release Notification and Corrective Action**OPERATOR**☒ Initial Report ☐ Final Report

Name of Company Yates Petroleum Corporation	OGRID Number 25575	Contact Robert Asher
Address 104 S. 4 TH Street	API Number 30-025-27620	Telephone No. 505-748-1471
Facility Name Billbrey SWD #1	Facility Type Battery	
Surface Owner Federal	Mineral Owner Federal	Lease No. NM-105220

LOCATION OF RELEASE

Unit Letter B	Section 5	Township 22S	Range 32E	Feet from the 660	North/South Line North	Feet from the 1980	East/West Line East	County Lea
------------------	--------------	-----------------	--------------	----------------------	---------------------------	-----------------------	------------------------	---------------

Latitude 32.42597 Longitude 103.69426**NATURE OF RELEASE**

Type of Release Crude Oil & Produced Water	Volume of Release 10 B/O & 30 B/PW	Volume Recovered 5 B/O & 20 B/PW
Source of Release Water Pump	Date and Hour of Occurrence 9/7/2006 - PM	Date and Hour of Discovery 9/7/2006 - PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Pat Caperton, OCD District I	
By Whom? Robert Asher, Environmental Regulatory Agent, YPC	Date and Hour 9/8/2006, 9:16 AM (Telephone) & 9/8/2006, 9:18 AM (E-mail)	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* Water pump unable to keep up with rate of water coming into tanks. Vacuum truck called, overflow stopped. All fluids contained within berm.		
Describe Area Affected and Cleanup Action Taken.* An approximate area of 125' X 12', inside berm. Contaminated soils to be excavated and taken to Lea Land. Area to be evaluated. Depth to Ground Water: >100'; Wellhead Protection Area: No; Distance to Surface Water Body: >1000'; SITE RANKING IS 0.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Robert Asher	Approved by District Supervisor:	
Title: Environmental Regulatory Agent	Approval Date:	Expiration Date:
E-mail Address: boba@ypcnm.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: Thursday, September 14, 2006	Phone: 505-748-1471	

* Attach Additional Sheets If Necessary

incident - nPAC0626347250
application - pPAC0626347615

RP#1039