

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action


OPERATOR		<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Name of Company ChevronTexaco		Contact Danny Lovell	
Address 2401 Ave "O" Eunice NM 88221		Telephone No. 505-394-1242	
Facility Name EMSU #187		Facility Type WTW	
Surface Owner Beta Tibbis		Mineral Owner	Lease No.

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	5	21S	36E	654	NORTH	660	WEST	LEA

Latitude N32deg-31.225 Longitude W103deg-17.621

NATURE OF RELEASE

Type of Release PRODUCED WATER	Volume of Release 180BBLS	Volume Recovered 160BBLS
Source of Release WATER INJECTION LINE	Date and Hour of Occurrence 8/2/04 6:00am-5:00 pm	Date and Hour of Discovery 8/2/04-5:00 P.M.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? SYLVIA DICKEY	
By Whom? DANNY LOVELL	Date and Hour 10:00 A.M. 8/3/04	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* LATERAL LINE GOING TO WELL IS 2" FIBERGLASS AND IS CONNECTED TO WELLHEAD WITH 1" STAINLESS STEEL TUBING. TRACKS AROUND WELLHEAD INDICATED THAT A COW RUBBED AGAINST 1" SS CAUSING IT TO PULL OUT OF 2" FIBERGLASS COUPLING. WELL WAS SHUT-IN AND FLUID VACUUMED UP THAT EVENING.		
Describe Area Affected and Cleanup Action Taken.* MAJORITY OF FLUID WAS CONTAINED ON WELL PAD WITH A 120'X3' STRIP GOING INTO PASTURE. STAINED SOIL WAS SCRAPED UP AND HAULED TO RHINO LAND FARM. DEPTH TO GROUNDWATER 180'. PER RE-SUBMIT NOTICE CHEVRONTXACO WILL REMOVE CONTAMINATED SOIL FROM RHINO AND HAULED TO SUNDANCE DISPOSAL BY 10/30/04. VERTICAL EXTENT OF CONTAMINATED AREA WAS NOT REQUESTED WHEN SPILL WAS CALLED IN. XTO PURCHASED PROPERTY FROM CHEVRON TEXACO 8/16/04. A COPY OF RE-SUBMIT NOTICE WAS GIVEN TO GUY HACKUS WITH XTO 10/27/04 WHO WILL FURNISH OTHER CLEAN UP REQUIREMENTS REQUESTED.		
NOTE- LATE RESPONSE WAS DUE TO NOTICE JUST BEING RECEIVED RECENTLY.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: 	OIL CONSERVATION DIVISION	
Printed Name: DANNY LOVELL	Approved by District Supervisor:	

incident in system
incident # n PRS 0431031135
application - pPAC 0627125515

RPT# 1043