

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company ConocoPhillips Company	Contact Kenneth N. Andersen	
Address 4001 Penbrook, Odessa, TX 79762-5917	Telephone No. 505.391.3158	
Facility Name EVGASU WELL # 3308-007	Facility Type Oil and Gas	
Surface Owner State of New Mexico	Mineral Owner State of New Mexico	Lease No API # 30-025-32219

LOCATION OF RELEASE

Unit Letter E	Section 33	Township 17S	Range 35E	Feet from the	North/South Line	Feet from the	East/West Line	County Lea
-------------------------	----------------------	------------------------	---------------------	---------------	------------------	---------------	----------------	----------------------

Latitude **32.79347N** Longitude **-103.47073W**

NATURE OF RELEASE

Type of Release Crude Oil & Produced Water W/Chlorides = 58,000mg/L	Volume of Release 18.2 bbl (2 oil, 16.2 water)	Volume Recovered (2 oil, 12 water)
Source of Release 2 7/8" Flowline	Date and Hour of Occurrence 10/05/2006 0900hrs	Date and Hour of Discovery 10/05/2006 1515hrs
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* The cause of the spill was a flow line leak due to internal corrosion. The failed section of flow line will be replaced.		
Describe Area Affected and Cleanup Action Taken.* 18'X126' of dry black soil/caliche rock pasture with no cows present. The spill site will be delineated and remediated in accordance with NMOCD guidelines.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: <i>Kenneth N. Andersen</i>	OIL CONSERVATION DIVISION	
Printed Name: Kenneth N. Andersen	Approved by District Supervisor:	
Title: HSER PSM Lead	Approval Date:	Expiration Date:
E-mail Address: ken.n.andersen@conocophillips.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 10/09/2006 Phone: 505.391.3158		

• Attach Additional Sheets If Necessary

incident - NPAC 0628650004
application - pPAC 0628650108

RP#1084