

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

### Release Notification and Corrective Action

#### OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Yates Petroleum Corporation	OGRID Number 25575	Contact Robert Asher
Address 104 S. 4 <sup>TH</sup> Street	AP1 Number 30-025-37438	Telephone No. 505-748-1471
Facility Name Van Dyke State Unit #1	Facility Type Battery	
Surface Owner Fee	Mineral Owner State	Lease No. V-6088

#### LOCATION OF RELEASE

Unit Letter O	Section 17	Township 10S	Range 33E	Feet from the 330	North/South Line North	Feet from the 1980	East/West Line East	County Lea
------------------	---------------	-----------------	--------------	----------------------	---------------------------	-----------------------	------------------------	---------------

-50' (30')

Latitude 33.44098 Longitude 103.58810

#### NATURE OF RELEASE

Type of Release Crude Oil	Volume of Release 5.0 B/O	Volume Recovered 2.5 B/O
Source of Release Heater Dump	Date and Hour of Occurrence 9/29/2006 AM	Date and Hour of Discovery 9/29/2006 AM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? N/A	
By Whom? N/A	Date and Hour N/A	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.\*

N/A



Describe Cause of Problem and Remedial Action Taken.\*

Heater dump stuck open putting all production into water tank, not enough room in tank.

Describe Area Affected and Cleanup Action Taken.\*

An approximate area of 4' X 30'. All fluids contained within berm. Picked up standing fluids, contaminated soils were excavated, hauled to an OUCD approved land facility. Vertical and horizontal delineation will be made and corrective action taken. **Depth to Ground Water: < 50'; Wellhead Protection Area: No; Distance to Surface Water Body: > 1000'; SITE RANKING IS 20.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOC marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOC acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Robert Asher	Approved by District Supervisor: 	
Title: Environmental Regulatory Agent	Approval Date: 11-20-06	Expiration Date: 2-20-07
E-mail Address: boba@ypcnm.com	Conditions of Approval: SUBMIT FINAL C-141	Attached: <input type="checkbox"/>
Date: Friday, October 13, 2006	Phone: 505-748-1471	

\* Attach Additional Sheets If Necessary

Facility # PAC0628648964  
Incident - nPAC0628649069  
Application - pPAC0628649180

RPT# 1085