

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Yates Petroleum Corporation	OGRID Number 25575	Contact Robert Asher
Address 104 S. 4 TH Street	API Number 30-025-31889	Telephone No. 505-748-1471
Facility Name Kiwi AKX State #8	Facility Type Battery	
Surface Owner State	Mineral Owner State	Lease No. VB-134



LOCATION OF RELEASE

Unit Letter F	Section 16	Township 22S	Range 32E	Feet from the 1980	North/South Line North	Feet from the 2310	East/West Line West	County Lea
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	---------------

300' GW

Latitude 32.39337 Longitude 103.68028

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 250 B/PW	Volume Recovered 40 B/PW
Source of Release Discharge Line	Date and Hour of Occurrence 11/6/2006 - AM	Date and Hour of Discovery 11/6/2006 - AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Pat Caperton, OCD District I	
By Whom? Robert Asher, Environmental Regulatory Agent, YPC	Date and Hour 11/6/2006, 4:22 PM (Telephone) & 11/6/2006, 4:10 PM (Site)	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* Discharge line split at well head. Pump shut down/valves closed, vacuum truck called. Berm has been constructed around well pad.		
Describe Area Affected and Cleanup Action Taken.* An approximate area of 50' X 300', well pad and off location. Vertical and horizontal delineation will be made and corrective action taken. Depth to Ground Water: >100'; Wellhead Protection Area: No; Distance to Surface Water Body: >1000'; SITE RANKING IS 0.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Robert Asher	Approved by District Supervisor: 	
Title: Environmental Regulatory Agent	Approval Date: 11.18.06	Expiration Date: 2.18.07
E-mail Address: boba@ypcnm.com	Conditions of Approval: ADD 1 REP TO FILE SUBMIT SUBMIT Final C-141	Attached: 2
Date: Friday, November 10, 2006	Phone: 505-748-1471	

* Attach Additional Sheets If Necessary

Incident - nPAC0631746696
application - pPAC0631746834

RP#1119